
## **CEDARVIEW PROCESSOR (DMI)**



Cedarview M: remove these capacitors to support DMI x2. Cedarview D: Solder these capacitors to support DMI x4.

