December 17, 2010

RE: ATCB010001 - Original Equipment & Single Certification Applications (model: 104441-02)

FCC ID: YYU104441 & IC: 9356A-104441 for College Park Industries, Inc.

The following is in response to questions raised on the above referenced application.

1. The submitted user manual contains no instructions for changing or replacing the antenna on this device but several antennas are being offered with this device. Please either provide a manual that contains antenna installation/changing instructions or the reason why they are not required in the user manual for this device.

The manufacturer intends to sell the product with the antenna to be used already installed. The end user will not be provided with a range of antennas nor will they be expected to change the antenna on the product. Changes to the antenna used with the product after sale would be done only by a College Park technician (i.e. professional installer), and only if a particular installation requires a different antenna to optimize system performance. A professional installer manual is now included with this application.

2. The submitted user manual is also missing the statements for detachable antennas from Sections 7.1.4 and 7.1.5 of RSS-Gen Issue 2 dated June 2007. Please provide a user manual with the required statements or specify why they are not required for this device.

The manufacturer does not consider the antenna on this product to be detachable nor selectable by the end user. Note that the RP-SMA connector is inside the product housing and requires that the housing be dismantled to change the antenna. All antennas deployed with this product will be professionally installed by a College Park technician.