Internal photographs of equipment under test Top of Transmitter module without shield in place



## Bottom side of Transmitter module



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

ARC Wireless LLC Model: ARCFlex 802.11bgn Module

Test #: 110826


Test to: CFR47 (15.247) File: IntPho ARCFlex SN: ENG1 FCC ID#: Z2B-AFM1 Date: September 27, 2011

Page 1 of 4

Top of Transmitter module without shield in place



## Bottom side of Transmitter module



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

ARC Wireless LLC Model: ARCFlex 802.11bgn Module

Test #: 110826


Test to: CFR47 (15.247) File: IntPho ARCFlex


SN: ENG1

FCC ID#: Z2B-AFM1 Date: September 27, 2011

Page 2 of 4

## support interface boards





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

ARC Wireless LLC

Model: ARCFlex 802.11bgn Module


Test #: 110826

Test to: CFR47 (15.247) File: IntPho ARCFlex SN: ENG1

FCC ID#: Z2B-AFM1 Date: September 27, 2011

Page 3 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

ARC Wireless LLC

Model: ARCFlex 802.11bgn Module

Test #: 110826

Test to: CFR47 (15.247) File: IntPho ARCFlex SN: ENG1

FCC ID#: Z2B-AFM1 Date: September 27, 2011

Page 4 of 4