


page 1 of 4

ANNEX B INTERNAL PHOTOS



113483_9: MOSI16B, top view


 Examiner:
 Manuel BASTERT
 Test Report No.:
 F113483E1

 Date of issue:
 14 June 2012
 Order No.:
 11-113483



page 2 of 4

ANNEX B INTERNAL PHOTOS



113483_10: MOSI16B, bottom view


 Examiner:
 Manuel BASTERT
 Test Report No.:
 F113483E1

 Date of issue:
 14 June 2012
 Order No.:
 11-113483



page 3 of 4

ANNEX B INTERNAL PHOTOS



113483_7: MOSI16B mounted on carrier board, top view


Test Report No.: F113483E1 Order No.: F113483

Examiner: Manuel BASTERT Date of issue: 14 June 2012



page 4 of 4

ANNEX B INTERNAL PHOTOS



113483_8: Carrier board, bottom view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F113483E1

 Date of issue:
 14 June 2012
 Order No.:
 11-113483