


ANNEX B INTERNAL PHOTOS



113482_1: MOSI09B, PCB, top view


 Examiner:
 Manuel BASTERT
 Test Report No.:
 F113482E1

 Date of issue:
 11 June 2012
 Order No.:
 11-113482
 page 1 of 4



page 2 of 4

ANNEX B INTERNAL PHOTOS




113482_2: MOSI09B, PCB, bottom view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F113482E1

 Date of issue:
 11 June 2012
 Order No.:
 11-113482



ANNEX B INTERNAL PHOTOS



113482_5: MOSI09B mounted on carrier board, top view


Examiner: Manuel BASTERT Date of issue: 11 June 2012 Test Report No.: F113482E1 Order No.: F113482

page 3 of 4



page 4 of 4

ANNEX B INTERNAL PHOTOS



113482_6: Carrier board, bottom view

Test Report No.: F113482E1 Order No.: F113482

Examiner: Manuel BASTERT Date of issue: 11 June 2012