

Report No.: 14020513-FCC-E1 Issue Date: September 11, 2014 Page: 26 of 43

Page: 26 of 43 www.siemic.com www.sinmic.com.cn

## Annex B.ii. **Photograph 2: EUT Internal Photo**




Cover Off - Top View 1




Cover Off - Top View 2

Report No.: 14020513-FCC-E1 Issue Date: September 11, 2014 Page: 27 of 43 www.siemic.com www.sinmic.com.cn




Mainboard - Front View




Mainboard - Rear View

Report No.: 14020513-FCC-E1 Issue Date: September 11, 2014 Page: 28 of 43 Page: 28 of www.siemic.com




Connect board 1 - Front View




Connect board 1 - Rear View

Report No.: 14020513-FCC-E1 Issue Date: September 11, 2014 Page: 29 of 43 www.siemic.com



Connect board 2 - Front View




Connect board 2 - Rear View

Report No.: 14020513-FCC-E1 Issue Date: September 11, 2014 Page: 30 of 43 www.siemic.com


The control of the co

Connect board 3 - Front View




Connect board 3 - Rear View

Report No.: 14020513-FCC-EI Issue Date: September 11, 2014 Page: 31 of 43 www.siemic.com




Two Same Connect board 4 - Front View




Connect board 4 - Front View

Report No.: 14020513-FCC-E1 Issue Date: September 11, 2014 Page: 32 of 43

www.siemic.com




Connect board 4 - Rear View




Two Same Connect board 5 - Front View

Report No.: 14020513-FCC-E1 Issue Date: September 11, 2014 Page: 33 of 43 www.siemic.com



Connect board 5 - Front View




Connect board 5 - Rear View


FCC Part 15 Subpart B Class B: 2013, ANSI C63.4:2009

Report No.: 14020513-FCC-E1 Issue Date: September 11, 2014 Page: 34 of 43

Page: 34 of www.siemic.com




Two Same Connect board 6 - Front View



Connect board 6 - Front View



Report No.: 14020513-FCC-E1 Issue Date: September 11, 2014 Page: 35 of 43 www.siemic.com



Connect board 6 - Rear View