

Report No.: FR4O0971E

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: Z64-WL18DBMOD Page Number : C1 of C2
Report Issued Date : Dec. 19, 2014
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL Version 1.0






Report No. : FR4O0971E


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: Z64-WL18DBMOD Page Number : C2 of C2
Report Issued Date : Dec. 19, 2014
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL Version 1.0