

Appendix B. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: Z64-WL18DBMOD Page Number : B1 of B2
Report Issued Date : Dec. 19, 2014
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.0

Report No.: FR4O0971A




Report No.: FR4O0971A

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: Z64-WL18DBMOD Page Number : B2 of B2
Report Issued Date : Dec. 19, 2014
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.0