

Report No.: FR4O2349C

Appendix D. Setup Photographs

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: Z64-WL18SBMOD Page Number : D1 of D1
Report Issued Date : Sep. 04, 2015
Report Version : Rev. 01

Report Template No.: BU5- CR247WL2.4G MA Version 1.0