

Texas Instruments Incorporated 12500 T.I. BLVD Dallas, TX 75243

December 15, 2014

FCC Laboratory 7435 Oakland Mills Rd. Columbia, MD 21046

SUBJECT: FCC Application for FCC ID: Z64-WL18DBMOD

In accordance with §15.407(j), we acknowledge that should any harmful interference generated by FCC ID: Z64-WL18DBMOD to licensed services in 5.15-5.25 GHz, corrective action is required to be taken. Corrective actions may include reducing power, turning off devices, changing frequency bands, and/or further reducing power radiated in the vertical direction.

Sincerely yours,

Contact Person: Kelley J. Foltz

Texas Instruments, Inc. EPD EVM Planning Manager

214-882-9119 FOLTZ@ti.com