

Report No. : FR4O0971C

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: Z64-WL18DBMOD Page Number : B1 of B2
Report Issued Date : Dec. 19, 2014
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.0




Report No.: FR4O0971C

<Radiated Emission>

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: Z64-WL18DBMOD Page Number : B2 of B2
Report Issued Date : Dec. 19, 2014
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.0