

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z6SKEYPAD Page Number : B1 of B2
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01


Report No. : FR150902



Report No. : FR150902

<Radiated Emission>





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z6SKEYPAD Page Number : B2 of B2
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01