
3. Internal Photograph of EUT

Brand Name: SaFPWR /

Model Name: K2P-K601, K2P-K602, K2P-K603, K2P-K604, K2P-K605, K2P-K606, K2P-K607, K2P-K608, K2P-K609, K2P-K610, K2P-K611, K2P-K612, K2P-K613, K2P-K614, K2P-K615, K2P-K616, K2P-K617,

K2P-K618, K2P-K619, K2P-K620




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z6SKEYPAD Page Number : 11 of 18
Report Issued Date : Oct. 24, 2011

Report No.: EP150902


Report Version : Rev. 01

Model Name: K2P-K601, K2P-K602, K2P-K603, K2P-K604, K2P-K605, K2P-K606, K2P-K607, K2P-K608, K2P-K609, K2P-K610, K2P-K611, K2P-K612, K2P-K613, K2P-K614, K2P-K615, K2P-K616, K2P-K617, K2P-K618, K2P-K619, K2P-K620



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z6SKEYPAD Page Number : 12 of 18
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Model Name: K2P-K601, K2P-K602, K2P-K603, K2P-K604, K2P-K605, K2P-K606, K2P-K607, K2P-K608, K2P-K609, K2P-K610, K2P-K611, K2P-K612, K2P-K613, K2P-K614, K2P-K615, K2P-K616, K2P-K617, K2P-K618, K2P-K619, K2P-K620




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z6SKEYPAD Page Number : 13 of 18
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

otographs of EUT Report No.: EP150902


Brand Name: SaFPWR /

Model Name: K2P-K601, K2P-K602, K2P-K603, K2P-K604, K2P-K605, K2P-K606, K2P-K607, K2P-K608, K2P-K609, K2P-K610, K2P-K611, K2P-K612, K2P-K613, K2P-K614, K2P-K615, K2P-K616, K2P-K617, K2P-K618, K2P-K619, K2P-K620




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z6SKEYPAD Page Number : 14 of 18
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Model Name: K2P-K601, K2P-K602, K2P-K603, K2P-K604, K2P-K605, K2P-K606, K2P-K607, K2P-K608, K2P-K609, K2P-K610, K2P-K611, K2P-K612, K2P-K613, K2P-K614, K2P-K615, K2P-K616, K2P-K617, K2P-K618, K2P-K619, K2P-K620




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z6SKEYPAD Page Number : 15 of 18
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Model Name: K2P-K601, K2P-K602, K2P-K603, K2P-K604, K2P-K605, K2P-K606, K2P-K607, K2P-K608, K2P-K609, K2P-K610, K2P-K611, K2P-K612, K2P-K613, K2P-K614, K2P-K615, K2P-K616, K2P-K617, K2P-K618, K2P-K619, K2P-K620



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z6SKEYPAD Page Number : 16 of 18
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01


Model Name: K2P-K601, K2P-K602, K2P-K603, K2P-K604, K2P-K605, K2P-K606, K2P-K607, K2P-K608, K2P-K609, K2P-K610, K2P-K611, K2P-K612, K2P-K613, K2P-K614, K2P-K615, K2P-K616, K2P-K617, K2P-K618, K2P-K619, K2P-K620



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z6SKEYPAD Page Number : 17 of 18
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Model Name: K2P-K601, K2P-K602, K2P-K603, K2P-K604, K2P-K605, K2P-K606, K2P-K607, K2P-K608, K2P-K609, K2P-K610, K2P-K611, K2P-K612, K2P-K613, K2P-K614, K2P-K615, K2P-K616, K2P-K617,

K2P-K618, K2P-K619, K2P-K620



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z6SKEYPAD Page Number : 18 of 18
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01