


M/N: DT-330



PCB Antenna disconnection does not work