Test report No.: 32BE0326-SH-01-A

: 31 of 33 Page

Issued date : December 5, 2011 : Z7W-TWE-001 FCC ID

## **APPENDIX 3: Photographs of test setup**

### **Conducted emission**





Side view



## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 +81 463 50 6401 Facsimile

Test report No.: 32BE0326-SH-01-A

Page : 32 of 33

Issued date : December 5, 2011 FCC ID : Z7W-TWE-001

#### **Radiated emission**







## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401


Test report No.: 32BE0326-SH-01-A


Page : 33 of 33

Issued date : December 5, 2011 FCC ID : Z7W-TWE-001

### Pre-check of the worst position







# UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401