
: 18 of 21 Page

Issued date : December 21, 2011 : Z7W-TWE-001 FCC ID

APPENDIX 3: Photographs of test setup

Conducted emission





Side view



UL Japan, Inc. **Shonan EMC Lab.**


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile +81 463 50 6401


Page : 19 of 21

Issued date : December 21, 2011 FCC ID : Z7W-TWE-001

Radiated emission







UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401


Page : 20 of 21

Issued date : December 21, 2011 FCC ID : Z7W-TWE-001

Pre-check of the worst position (Module)







UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Page : 21 of 21

Issued date : December 21, 2011 FCC ID : Z7W-TWE-001

Pre-check of the worst position (Antenna)





UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401