





Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 29 SEP 2017 10:40:19


Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 29.SEP.2017 10:40:34


Page No.

: 250 of 391






Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 1GHz~3GHz




Date: 29.SEP 2017 10:40:52

Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 1GHz~3GHz




Date: 29.SEP.2017 10:41:07

Page No. : 251 of 391






Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 29.SEP.2017 10:41:23

Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 29.SEP.2017 10:41:40

: 252 of 391 Page No. Issued Date : Nov. 06, 2017






Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 3GHz~6GHz



Date: 2.OCT.2017 23:40:25

Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 3GHz~6GHz




Date: 2.OCT.2017 23:44:29

FCC ID: Z8H89FT0038


Page No.

: 253 of 391






Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 2.OCT.2017 23:40:59

Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 3GHz~6GHz




Date 2.00T.2017 23.44.58

FCC ID: Z8H89FT0038


Page No.

: 254 of 391






Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.OCT.2017 00:01;02

Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 3GHz~6GHz




Date: 2.OCT.2017 23:57;20

FCC ID: Z8H89FT0038


Page No.

: 255 of 391






Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 3GHz \sim 6GHz




Date: 3.OCT,2017 00:01:38

Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 3GHz~6GHz





Date: 2.OCT.2017, 23:59.04

Page No. : 256 of 391 Issued Date : Nov. 06, 2017 FCC ID: Z8H89FT0038










Date: 3.OCT.2017 00:06;35

Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 3GHz~6GHz




Date: 3.OCT,2017 00,14:13

FCC ID: Z8H89FT0038


Page No.

: 257 of 391






Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 3.OCT.2017 00:07:15


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 3.OCT.2017 00:15:13


Page No. : :

: 258 of 391






Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.OCT.2017 00:58:37

Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 3GHz~6GHz




Date: 9.OCT.2017 01:07:03

FCC ID; Z8H89FT0038


Page No.

: 259 of 391










Date: 3.OCT,2017 01:04:05

Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.OCT,2017 01;07;50

FCC ID: Z8H89FT0038


Page No.

: 260 of 391






Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.OCT.2017 01:25:20

Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 3GHz~6GHz




Date: 3.OCT.2017 01;27:33

FCC ID: Z8H89FT0038

Issued Date : Nov. 06, 2017


Page No.

: 261 of 391






Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 3.OCT.2017 01;25;53

Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.OCT.2017 01:27:59

Page No. : 262 of 391






Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.0 CT 2017 10:59:41

Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 3GHz~6GHz




Date: 3.0 CT 2017 12:07:21

FCC ID: Z8H89FT0038

Issued Date : Nov. 06, 2017


Page No.

: 263 of 391






Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 3.0 CT 2017 11:00:35

Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.0 CT 2017 11:37:22

FCC ID; Z8H89FT0038


Page No.

: 264 of 391






Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.0 CT 2017 14 28 25

Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 3GHz \sim 6GHz



Date: 3.0 CT 2017 14:32:05


FCC ID: Z8H89FT0038

Page No.

: 265 of 391




Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 3.0 CT.2017 14:29:01

Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 3.0 CT 2017 14:31:19

FCC ID: Z8H89FT0038


Page No.

: 266 of 391




Report No.: FR7O1623

Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.0 CT.2017 11:41:36

Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 3GHz~6GHz




Date: 3.0 CT 2017 11:58:57

Report Format Version: Rev. 01


FCC ID: Z8H89FT0038

Page No. : 267 of 391










Date: 3.0 CT 2017 11:42:02


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 3.0 CT.2017 11:43:43


FCC ID: Z8H89FT0038

Page No. : 268 of 391 Issued Date : Nov. 06, 2017






Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.0 CT.2017 11:47:16

Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 3GHz~6GHz




Date: 3.0 CT 2017 14:34:25

FCC ID: Z8H89FT0038


Page No.

: 269 of 391






Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 3.0 CT 2017 11:47:55

Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.0 CT 2017 11:50:05

FCC ID: Z8H89FT0038


Page No.

: 270 of 391






Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 3GHz~6GHz




Date: 3.0 CT 2017 11:51:30

Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 3GHz~6GHz




Date: 3.0 CT 2017 11:53:29

Page No. : 271 of 391






Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 3.0 CT.2017 11:51:56

Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.0 CT 2017 11:53:04

FCC ID: Z8H89FT0038


Page No.

: 272 of 391






Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.0 CT 2017 11:54:57

Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 3GHz~6GHz




Date: 3.0 CT 2017 11:57:04

FCC ID: Z8H89FT0038


Page No.

: 273 of 391










Date: 3.0 CT 2017 11:55:18


Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 3.0 CT.2017 11:56:33


Page No.

: 274 of 391






Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 6GHz \sim 9GHz



Date: 29.SEP.2017 16:37:10

Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 6GHz~9GHz



Date: 29.SEP 2017 16:40:41

FCC ID: Z8H89FT0038


Page No.

: 275 of 391






Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 29 SEP 2017 16:38:37

FCC ID: Z8H89FT0038


Page No.

: 276 of 391






Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 6GHz~9GHz




Date: 29.SEP.2017 16:38:53

Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 6GHz~9GHz




Date: 29.SEP.2017 16:39:24

Page No. : 277 of 391






Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 29 SEP 2017 16:40:14

FCC ID: Z8H89FT0038


Page No.

: 278 of 391






Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 6GHz~9GHz




Date: 29.SEP.2017 16:41:21

Piot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 6GHz~9GHz




Date: 29.SEP 2017 16:41:34

Page No. : 279 of 391






Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 29.SEP.2017 16:41:51


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 29.SEP.2017 16:42:04


Page No.

: 280 of 391






Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 6GHz~9GHz



Date: 29.SEP.2017 21:46:38


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 6GHz~9GHz



Date: 29.SEP.2017 21:47:01


Page No. : 281 of 391

FCC ID: Z8H89FT0038






Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 29.SEP.2017 21:47:31

Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 29 SEP .2017 21:47:59

Page No. : 282 of 391






Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 6GHz~9GHz



Date: 29.SEP.2017 21:48:36

Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 6GHz~9GHz




Date: 29.SEP.2017 21:48:54


FCC ID: Z8H89FT0038


Page No.

: 283 of 391










Date: 29.SEP.2017 21:49:28


Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 29.5EP.2017 21:50:01


Page No. : 284 of 391

FCC ID: Z8H89FT0038






Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 6GHz~9GHz



Date: 28.5EP.2017 09:02:28

Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 6GHz~9GHz



Date: 28.SEP.2017 09:02:49


FCC ID: Z8H89FT0038

Page No. : 285 of 391 Issued Date : Nov. 06, 2017






Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 28.SEP 2017 09:03:17

Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 28.SEP.2017 09:03:32

FCC ID: Z8H89FT0038


Page No.

: 286 of 391






Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 6GHz~9GHz



Date: 28 SEP 2017 09:04:19

Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 6GHz~9GHz




Date: 28.SEP.2017 09:04:40

FCC ID: Z8H89FT0038


Page No.

: 287 of 391






Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 28.SEP 2017 09:04:57

Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 28.SEP 2017 09:06:01


Page No.

: 288 of 391




Report No.: FR7O1623

Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 6GHz~9GHz



Date: 28.SEP.2017 09:06:57

Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 6GHz \sim 9GHz




Date: 28.SEP.2017 09:07:13

FCC ID: Z8H89FT0038


Page No.

: 289 of 391






Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 28.SEP.2017 09:07:44

Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 28.SEP.2017 09:08:03

FCC ID: Z8H89FT0038


Page No.

: 290 of 391






Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 6GHz~9GHz




Date: 29 SEP 2017 11:23:51

Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 6GHz~9GHz




Date: 29.SEP 2017 10:33:17

Page No. : 291 of 391 FCC ID: Z8H89FT0038 Issued Date : Nov. 06, 2017






Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 29.SEP.2017 10:33:48

Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 29.SEP 2017 10:34:04

FCC ID: Z8H89FT0038


Page No.

: 292 of 391






Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 6GHz~9GHz



Date: 29.SEP.2017 10:34:48


Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 6GHz~9GHz




Date: 29.SEP 2017 10:35:07


Page No.

: 293 of 391










Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 29 SEP 2017 10:36:02

FCC ID: Z8H89FT0038


Page No.

: 294 of 391






Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 6GHz~9GHz



Date: 29.SEP.2017 10:36:22


Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 6GHz~9GHz



Date: 29.SEP.2017 10:36:38


FCC ID: Z8H89FT0038 Issued

Page No. : 295 of 391










Date: 29.SEP.2017 10:36:58

Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 29.SEP.2017 10:37:13

FCC ID: Z8H89FT0038


Page No.

: 296 of 391






Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 9GHz~18GHz



Date: 29.SEP.2017 16:49:51

Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 9GHz~18GHz




Date: 29.SEP.2017 16:49:13

FCC ID: Z8H89FT0038


Page No.

: 297 of 391






Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 29.SEP.2017 16:50:14

Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 29.SEP.2017 16:50:29

Page No. : 298 of 391






Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 9GHz~18GHz



Date: 29 SEP .2017 16:51:13

Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 9GHz~18GHz



Date: 29.SEP 2017 16:51:36

Page No. : 299 of 391