



Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 3GHz~6GHz_Emission in Non-restriction band

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 3GHz~6GHz_Emission in Non-restriction band


Plot on Configuration QPSK, 80M / 5520 MHz / Average / Port 1 / 3GHz~6GHz




Date: 29.NOV.2017 17:56:09

Plot on Configuration QPSK, 80M / 5520 MHz / Average / Port 2 / 3GHz~6GHz



Date: 29.NOV.2017 17:58:19

Plot on Configuration QPSK, 80M / 5520 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5520 MHz / Peak / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 3GHz~6GHz




Date: 29.NOV.2017 18:04:13

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 3GHz~6GHz




Date: 29.NOV.2017 18:01:06

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 3GHz~6GHz




Date: 29.NOV.2017 18:06:05

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 3GHz~6GHz




Date: 29.NOV.2017 18:07:38

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 29.NOV.2017 18:06:25

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 29.NOV.2017 18:07:57


Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 2.DEC.2017 00:45:47

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 2.DEC.2017 00:51:19

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 3GHz~6GHz_Emission in Non-restriction band




Date: 29.NOV.2017 17:44:46

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 29.NOV.2017 17:26:14

Plot on Configuration QPSK, 20M / 5510 MHz / Peak / Port 1 / 3GHz~6GHz_Emission in Non-restriction band




Date: 29.NOV.2017 17:57:13

Plot on Configuration QPSK, 20M / 5510 MHz / Peak / Port 2 / 3GHz~6GHz_Emission in Non-restriction band




Date: 29.NOV.2017 17:59:02

Plot on Configuration QPSK, 20M / 5610 MHz / Peak / Port 1 / 3GHz~6GHz_Emission in Non-restriction band




Date: 29.NOV.2017 18:05:06


Plot on Configuration QPSK, 20M / 5610 MHz / Peak / Port 2 / 3GHz~6GHz_Emission in Non-restriction band



Date: 29.NOV.2017 18:02:37


Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 3GHz~6GHz_Emission in Non-restriction band


Date: 29.NOV.2017 18:06:38

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 3GHz~6GHz_Emission in Non-restriction band



Date: 29.NOV.2017 18:08:11

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 3GHz~6GHz_Emission in Non-restriction band





Date: 2.DEC.2017 00:46:17


Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 3GHz~6GHz_Emission in Non-restriction band




Date: 2.DEC.2017 00:51:42


Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 6GHz~9GHz

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 6GHz~9GHz


Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 6GHz~9GHz


Date: 28 NOV. 2017 01:03:29

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 6GHz~9GHz



Date: 28 NOV. 2017 01:14:00

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 28 NOV. 2017 01:04:02


Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 28 NOV. 2017 01:14:25


Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 6GHz~9GHz


Date: 28 NOV. 2017 01:25:04


Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 6GHz~9GHz



Date: 28 NOV. 2017 01:36:02

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 6GHz~9GHz


Date: 28 NOV. 2017 02:33:01

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 6GHz~9GHz



Date: 28 NOV. 2017 02:44:17

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 28 NOV. 2017 02:33:54

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 28 NOV. 2017 02:44:39


Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 6GHz~9GHz


Date: 28 NOV. 2017 01:48:30

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 6GHz~9GHz



Date: 28 NOV. 2017 02:01:27

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 6GHz~9GHz





Date: 28 NOV. 2017 01:49:04


Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 28 NOV. 2017 02:02:08



Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 6GHz~9GHz

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 6GHz~9GHz


Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 6GHz~9GHz





Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 6GHz~9GHz

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 6GHz~9GHz


Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 6GHz~9GHz


Date: 1.DEC.2017 19:38:30

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 6GHz~9GHz



Date: 1.DEC.2017 19:53:58

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 1.DEC.2017 19:39:03

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 1.DEC.2017 19:54:31


Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 1.DEC.2017 20:07:56

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 1.DEC.2017 20:22:53

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 6GHz~9GHz




Date: 1.DEC.2017 20:36:31

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 6GHz~9GHz





Date: 1.DEC.2017 20:55:23

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 6GHz~9GHz


Date: 1.DEC.2017 21:09:20

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 6GHz~9GHz



Date: 1.DEC.2017 21:27:27

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 1.DEC.2017 21:10:04

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 1.DEC.2017 21:31:34


Plot on Configuration QPSK, 80M / 5520 MHz / Average / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 80M / 5520 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5520 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 1.DEC.2017 21:59:13

Plot on Configuration QPSK, 80M / 5520 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 1.DEC.2017 22:15:02

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 6GHz~9GHz




Date: 1.DEC.2017 22:33:47

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 6GHz~9GHz




Date: 1.DEC.2017 22:56:42

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 1.DEC.2017 22:34:18

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 1.DEC.2017 22:57:41

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 6GHz~9GHz




Date: 1.DEC.2017 23:07:20

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 6GHz~9GHz




Date: 1.DEC.2017 23:22:52

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 1.DEC.2017 23.07.59

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 2.DEC.2017 00.36.39

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 6GHz~9GHz




Date: 2.DEC.2017 00:36:39

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 6GHz~9GHz




Date: 2.DEC.2017 00:56:52

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 2.DEC.2017 00:37:11


Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 2.DEC.2017 00:57:34


Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 9GHz~18GHz


Date: 28 NOV.2017 00:31:57


Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 9GHz~18GHz


Date: 28 NOV.2017 00:45:16


Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 28 NOV. 2017 01:05:34

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 28 NOV. 2017 01:12:25

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 28 NOV. 2017 01:06:12


Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 28 NOV. 2017 01:12:46


Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 9GHz~18GHz


Date: 28.NOV.2017 01:26:51

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 9GHz~18GHz



Date: 28.NOV.2017 01:34:25

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 9GHz~18GHz





Date: 28 NOV.2017 01:27:29


Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 28 NOV.2017 01:34:53

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 9GHz~18GHz

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 9GHz~18GHz




Date: 28 NOV. 2017 01:49:54

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 9GHz~18GHz




Date: 28 NOV. 2017 01:57:03

Plot on Configuration QPSK, 80M / 5290MHz / Peak / Port 1 / 9GHz~18GHz




Date: 28 NOV. 2017 01:50:12


Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 28 NOV. 2017 01:57:44


Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 9GHz~18GHz


Date: 28 NOV.2017 02:14:04

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 9GHz~18GHz



Date: 28 NOV.2017 02:20:12

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 28 NOV. 2017 02:14:39

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz





Date: 28 NOV. 2017 02:20:38

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 9GHz~18GHz





Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 28 NOV. 2017 02:57:13

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 28 NOV. 2017 03:03:56


Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 9GHz~18GHz

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 9GHz~18GHz


Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5580MHz / Average / Port 1 / 9GHz~18GHz


Date: 1.DEC.2017 20:02:08

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 9GHz~18GHz



Date: 1.DEC.2017 20:20:18

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 9GHz~18GHz





Date: 1.DEC.2017 20:02:51


Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 1.DEC.2017 20:18:56



Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 9GHz~18GHz

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 9GHz~18GHz


Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 9GHz~18GHz

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5520 MHz / Average / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5520 MHz / Average / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5520 MHz / Peak / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5520 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 1.DEC.2017 23:11:56

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 9GHz~18GHz


Date: 1.DEC.2017 23:20:38


Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 9GHz~18GHz


Date: 2.DEC.2017 00:38:46

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 9GHz~18GHz



Date: 2.DEC.2017 00:58:44

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 2.DEC.2017 00:39:17


Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 2.DEC.2017 00:59:32

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28 NOV. 2017 00:34:47

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 18GHz~40GHz




Date: 28 NOV. 2017 00:43:06



Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 28 NOV. 2017 00:35:22

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 28 NOV. 2017 00:44:14

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 18GHz~40GHz

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 18GHz~40GHz



Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz


Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28 NOV. 2017 01:29:09

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 18GHz~40GHz



Date: 28 NOV. 2017 01:32:33

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 28 NOV. 2017 01:30:08

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 28 NOV. 2017 01:33:01

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28 NOV. 2017 02:36:50

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 18GHz~40GHz



Date: 28 NOV. 2017 02:39:28

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 28 NOV. 2017 02:37:12

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 28 NOV. 2017 02:40:06

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28 NOV. 2017 01:51:39

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 18GHz~40GHz



Date: 28 NOV. 2017 01:55:13

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 28 NOV. 2017 01:52:24

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 28 NOV. 2017 01:55:58

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28 NOV. 2017 02:15:48

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 18GHz~40GHz




Date: 28 NOV. 2017 02:18:24


Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz


Date: 28 NOV. 2017 02:16:09


Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz


Date: 28 NOV. 2017 02:19:14


Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 18GHz~40GHz

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 18GHz~40GHz


Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 28 NOV. 2017 02:59:42

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 28 NOV. 2017 03:02:22

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 18GHz~40GHz



Date: 1.DEC.2017 19:45:28

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 18GHz~40GHz



Date: 1.DEC.2017 19:49:23

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 1.DEC.2017 19:46:02

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 1.DEC.2017 19:50:27


Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 18GHz~40GHz


Date: 1.DEC.2017 20:11:57


Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 18GHz~40GHz


Date: 1.DEC.2017 20:16:05



Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 18GHz~40GHz

Plot on Configuration QPSK, 20M / 5580MHz / Peak / Port 2 / 18GHz~40GHz



Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 18GHz~40GHz


Date: 1.DEC.2017 20:42:08


Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 18GHz~40GHz


Date: 1.DEC.2017 20:48:53

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 18GHz~40GHz

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 18GHz~40GHz



Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 18GHz~40GHz


Date: 1.DEC.2017 21:15:00

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 18GHz~40GHz



Date: 1.DEC.2017 21:21:17

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 1.DEC.2017 21:15:35


Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 18GHz~40GHz





Date: 1.DEC.2017 21:22:14



Plot on Configuration QPSK, 80M / 5520 MHz / Average / Port 1 / 18GHz~40GHz



Date: 1.DEC.2017 22:06:28

Plot on Configuration QPSK, 80M / 5520 MHz / Average / Port 2 / 18GHz~40GHz



Date: 1.DEC.2017 22:09:40

Plot on Configuration QPSK, 80M / 5520 MHz / Peak / Port 1 / 18GHz~40GHz

Plot on Configuration QPSK, 80M / 5520 MHz / Peak / Port 2 / 18GHz~40GHz


Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 18GHz~40GHz

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 18GHz~40GHz



Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 18GHz~40GHz


Date: 1.DEC.2017 22:39:34

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 1.DEC.2017 22:43:30

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 18GHz~40GHz




Date: 1.DEC.2017 23:13:54


Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 18GHz~40GHz





Date: 1.DEC.2017 23:17:24



Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 18GHz~40GHz


Date: 1.DEC.2017 23:14:37

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 1.DEC.2017 23:18:00

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 18GHz~40GHz

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 18GHz~40GHz


Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 18GHz~40GHz

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 18GHz~40GHz


For Antenna 3:


Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 1GHz~3GHz






Date: 30.NOV.2017 22:15:20

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 1GHz~3GHz




Date: 30.NOV.2017 22:35:45

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 1GHz~3GHz

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 1GHz~3GHz



Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 1GHz~3GHz


Date: 1.DEC.2017 00:11:32

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 1GHz~3GHz



Date: 1.DEC.2017 00:40:38

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 1.DEC.2017 00:13:35


Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 1GHz~3GHz





Date: 1.DEC.2017 00:41:17

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 1GHz~3GHz



Date: 1.DEC.2017 01:47:59

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 1GHz~3GHz


Date: 1.DEC.2017 02:12:08

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 1GHz~3GHz

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 1GHz~3GHz


Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 1GHz~3GHz




Date: 1.DEC.2017 10:46:47

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 1GHz~3GHz




Date: 1.DEC.2017 10:49:17


Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 1.DEC.2017 10:47:47

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 1.DEC.2017 10:50:28

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 1GHz~3GHz




Date: 4.DEC.2017 15.05.18

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 1GHz~3GHz




Date: 4.DEC.2017 15.23.14

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 4.DEC.2017 15.05.49

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 4.DEC.2017 15.23.44


Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 3GHz~6GHz


Date: 30.NOV.2017 20:56:22


Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 3GHz~6GHz


Date: 30.NOV.2017 21:14:53

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 3GHz~6GHz


Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 3GHz~6GHz


Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 30.NOV.2017 21:22:29

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 30.NOV.2017 22:10:43

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 3GHz~6GHz



Date: 30.NOV.2017 22:17:12

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 3GHz~6GHz




Date: 30.NOV.2017 22:33:01

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 30.NOV.2017 22:17:58

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 3GHz~6GHz


Date: 30.NOV.2017 22:33:59


Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 3GHz~6GHz

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 3GHz~6GHz


Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 1.DEC.2017 00:15:23

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 1.DEC.2017 00:38:51