

Dear EAS Admin,

The following FCC identifiers are affected and proposed to be changed:

<u>Original</u>					Proposed		
From:	Motor	Motorola Solutions			Cambium Networks		
<u>Date</u>	Grantee co	de/ Product Code		Grantee cod	de /Product Code	(Comment / Rule part)	
6/21/2004	ABZ	89fc5809	to:	Z8H	89fc5809	(900MHz FSK / Part 15C)	
11/25/2003	B ABZ	89fc5808	to:	Z8H	89fc5808	(2.4GHz FSK / Part 15C)	
12/19/2003	B ABZ	89fc5807	to:	Z8H	89fc5807	(5.2GHz FSK / Part 15E)	
6/4/2003	ABZ	89fc5804	to:	Z8H	89fc5804	(5.7GHz FSK / Part 15C)	
9/7/2001	ABZ	89fc3789	to:	Z8H	89fc3789	(5.2GHz FSK / Part 15E)	
7/27/2007	ABZ	89ft7623	to:	Z8H	89ft7623	(5.4GHz FSK / Part 15E)	
1/28/2009	ABZ	89ft7631	to:	Z8H	89ft7631	(4.9GHz OFDM / Part 90Y)	
8/06/2008	ABZ	89ft7630	to:	Z8H	89ft7630	(5.7GHz OFDM / Part 15C)	
2/25/2010	ABZ	89ft7632	to:	Z8H	89ft7632	(3.65GHz Wimax / Part 90)	
11/30/2009) ABZ	89ft7633	to:	Z8H	89ft7633	(3.65GHz Wimax / Part 90)	
11/10/2009) ABZ	89ft7634	to:	Z8H	89ft7634	(5.7GHz OFDM / Part 15C)	
11/10/2009) ABZ	89ft7635	to:	Z8H	89ft7635	(5.7GHz OFDM / Part 15C)	
9/22/2010	ABZ	89ft7636	to:	Z8H	89ft7636	(3.65GHz Wimax / Part 90)	
12/16/2010) ABZ	89ft7637	to:	Z8H	89ft7637	(5.4GHz OFDM / Part 15E)	
12/16/2010) ABZ	89ft7638	to:	Z8H	89ft7638	(5.4GHz OFDM / Part 15E)	

The equipment is still representative of the FCC filings, also no change in design, circuitry or construction is involved. Labels will only be changed after authorization from the commission. Please note the engineering staff remains the same.

I am the person authorized to make these changes. I have been involved as technical contact/Regulatory Engineer throughout the above products lifecycles.

My grantee code is currently on file with the FCC on behalf of Cambium Networks (1299 East Algonquin Rd Schaumburg Illinois 60196).

https://gullfoss2.fcc.gov/prod/oet/cf/eas/index.cfm link was not working, please help.

Regards,

Steve Payne

Principle Staff Engineer Cambium Networks Inc.

224-392-5930