





Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 3.OCT.2017 14:54:15


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 3.OCT.2017 14:56,00


Page No. : 152

: 152 of 391






Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.OCT.2017 14:58:27


Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 3GHz $\sim$ 6GHz



Date: 3.OCT.2017 15:01:40


Page No.

: 153 of 391






Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 3.OCT.2017 14:58:43

Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.OCT.2017 15:00:18

FCC ID: Z8H89FT0038


Page No.

: 154 of 391






Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.OCT.2017 15:05:50

Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 3GHz $\sim$ 6GHz




Date: 3,OCT.2017 15:08:48

FCC ID: Z8H89FT0038


Page No.

: 155 of 391






Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 3.OCT.20(7 15:06:32


Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 3.OCT.2017 15:08:22


Page No.

: 156 of 391






Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.OCT.2017 15:12:27

Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 3GHz~6GHz




Date: 3.OCT.2017 15:10:08

FCC ID: Z8H89FT0038


Page No. : 157

: 157 of 391






#### Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 3.OCT.2017 15;12:06


Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 3.OCT.2017 15:10,33


Page No.

: 158 of 391






Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 6GHz~9GHz



Date: 30 SEP 2017 08:06:54

Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 6GHz~9GHz




Date: 30 SEP 2017 08:08:09

FCC ID: Z8H89FT0038


Page No.

: 159 of 391






Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 30.SEP.2017 08:08:54


Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 30.SEP.2017 08:09:22


Page No.

: 160 of 391






Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 6GHz~9GHz



Date: 30 SEP 2017 08:10:02

Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 6GHz~9GHz




Date: 30 SEP 2017 08:16:14

FCC ID: Z8H89FT0038

Issued Date : Nov. 06, 2017


Page No.

: 161 of 391






## Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 30 SEP 2017 08:11:07

## Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 30.SEP.2017 08:11:40

FCC ID: Z8H89FT0038


Page No.

: 162 of 391






Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 6GHz~9GHz



Date: 30.SEP.2017 08:12:25

Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 6GHz~9GHz



Date: 30.SEP.2017 08:13:51


: 163 of 391

Page No.






## Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 30 SEP 2017 08:14:27

## Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 30.SEP.2017 08:15:21

Page No. : 164 of 391 FCC ID: Z8H89FT0038 Issued Date : Nov. 06, 2017











Date: 30.SEP.2017 10:57:44

Plot on Configuration QPSK, 80M / 5190 MHz / Average / Port 2 / 6GHz~9GHz




Date: 30.SEP 2017 10:58:24

Page No. : 165 of 391






## Plot on Configuration QPSK, 80M / 5190 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 30.SEP.2017 10:58:51

## Plot on Configuration QPSK, 80M / 5190 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 30 SEP 2017 10:59:14

FCC ID: Z8H89FT0038


Page No.

: 166 of 391










Date: 30.SEP.2017 11:01:08


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 6GHz~9GHz



Date: 30.SEP.2017 11:11:14


Page No. : 10

: 167 of 391






#### Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 30 SEP 2017 11:02:08

## Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 30.SEP.2017 11:02:34

Page No.

: 168 of 391


Report No.: FR7O1623

Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 6GHz~9GHz



Date: 30 SEP 2017 11:08:11


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 6GHz~9GHz



Date: 30 SEP 2017 11:08:45


FCC ID: Z8H89FT0038

Page No. : 169 of 391






## Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 30.SEP.2017 11:09:27

## Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 30.SEP.2017 11:09:55


FCC ID: Z8H89FT0038

Page No. : 170 of 391










Date: 28.SEP.2017 15:32:05


## Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 6GHz~9GHz



Date: 28.SEP.2017 15:32:20


Page No. : 171 of 391 Issued Date : Nov. 06, 2017

FCC ID: Z8H89FT0038






#### Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 28\_SEP.2017 15:32:36


#### Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 28.SEP.2017 15:32:49


Page No.

: 172 of 391










Date: 28.SEP 2017 15:33:36

## Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 6GHz $\sim$ 9GHz




Date: 28.SEP.2017 15:33:52

Page No.


: 173 of 391

FCC ID: Z8H89FT0038






# Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 28 SEP 2017 15:33:04

#### Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 28.SEP.2017 15:33:18

FCC ID: Z8H89FT0038


Page No.

: 174 of 391






Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 6GHz~9GHz



Date: 28.SEP.2017 15:34:08

Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 6GHz~9GHz




Date: 28.SEP.2017 15:34:24

Page No.


: 175 of 391

FCC ID: Z8H89FT0038






## Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 28.SEP.2017 15:35:19

## Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 28.SEP.2017 15:35:04


FCC ID: Z8H89FT0038


Page No.

: 176 of 391











Date: 28.SEP.2017 17:12:29

# Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 6GHz~9GHz




Date: 28.SEP.2017 17:12:46






## Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 28.SEP.2017 17:13:02

## Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 6GHz~9GHz





Date: 28 SEP 2017 17:13:30

Page No. : 178 of 391










Date: 28.SEP.2017 17:13:49


# Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 6GHz $\sim$ 9GHz



Date: 28.SEP.2017 17:14:04


Page No. : 179 of 391

FCC ID: Z8H89FT0038






## Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 28.SEP 2017 17:14:21

#### Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 28 SEP 2017 17:14:36


Page No.


Issued Date : Nov. 06, 2017

: 180 of 391










Date: 28 SEP 2017 17:15:48

Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 /  $6GHz \sim 9GHz$ 




Date: 28.SEP.2017 17:16:08

FCC ID: Z8H89FT0038


Page No.

: 181 of 391






## Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 28.SEP.2017 17:16:24

## Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 28.SEP.2017 17:16:40


Page No. : 1

: 182 of 391










Date: 30.SEP.2017 08:18:52

Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 9GHz $\sim$ 18GHz




Date: 30.SEP.2017 08:21:15

FCC ID: Z8H89FT0038


Page No.

: 183 of 391






## Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 30.SEP.2017 08:21:51

#### Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 30.SEP 2017 08 22 21

Issued Date : Nov. 06, 2017


Page No.

: 184 of 391






Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 9GHz~18GHz



Date: 30.SEP.2017 08:23:58

Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 9GHz~18GHz




Date: 30.SEP.2017 08:24:40

FCC ID: Z8H89FT0038


Page No.

: 185 of 391






# Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 30 SEP 2017 08:25:26

#### Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 30.SEP.2017 08:26:03

Page No. : 186 of 391










Date: 30 SEP 2017 08:27:20

Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 9GHz~18GHz




Date: 30.SEP.2017 08:28:03

FCC ID: Z8H89FT0038


Page No.

: 187 of 391






### Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 30.SEP.2017 08:28:38


# Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 30.SEP.2017 08:29:09


Page No.

: 188 of 391






Plot on Configuration QPSK, 80M / 5190 MHz / Average / Port 1 / 9GHz~18GHz



Date: 30.SEP.2017 11:13:27


Plot on Configuration QPSK, 80M / 5190 MHz / Average / Port 2 /  $9GHz\sim18GHz$ 



Date: 30.SEP.2017 11:14:33


Page No.

: 189 of 391






### Plot on Configuration QPSK, 80M / 5190 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 30 SEP 2017 11:25:15


### Plot on Configuration QPSK, 80M / 5190 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 30 SEP 2017 11:25:40


Page No.

: 190 of 391






Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 9GHz~18GHz



Date: 30 SEP 2017 112627


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 9GHz~18GHz



Date: 30 SEP.2017 11:27:01


Page No.

: 191 of 391






# Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 30 SEP.2017 11:27:30


### Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 30 SEP 2017 11:29:03


Page No.

: 192 of 391















Date: 30.SEP.2017 11:35:50


Page No. : 193 of 391

FCC ID: Z8H89FT0038






### Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 9GHz~18GHz




# Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 30.SEP.2017 11:42:01


Page No.

: 194 of 391










Date: 28.SEP.2017 15:36:13


Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 9GHz $\sim$ 18GHz



Date: 28.SEP .2017 15:36:42


Page No. : 195 of 391

FCC ID: Z8H89FT0038






### Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 28.SEP 2017 15:37:00


### Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 28.SEP.2017 15:37:16


Page No.

: 196 of 391











Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 9GHz $\sim$ 18GHz



Date: 28.SEP.2017 15:38:01


Page No.

: 197 of 391






### Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 28.SEP.2017 15:38:17

#### Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 28.SEP.2017 15:38:32


FCC ID: Z8H89FT0038


Page No.

: 198 of 391










Date: 28 SEP 2017 15:38:56

# Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 9GHz $\sim$ 18GHz




Date: 28 SEP 2017 15:39:22

Page No. : 199 of 391




## Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 9GHz $\sim$ 18GHz



Date: 28.SEP.2017 15:39:40

### Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 28.SEP.2017 15:39:55

Page No.

: 200 of 391




Plot on Configuration QPSK,  $80M / 5765 \ MHz / Average / Port 1 / 9GHz \sim 18GHz$ 



Date: 28.SEP.2017 17:17:20

Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 9GHz~18GHz



Date: 28.SEP 2017 17:17:43

FCC ID: Z8H89FT0038

Page No.

: 201 of 391