






Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 1GHz~3GHz






Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 1GHz~3GHz




Date: 19.NOV.2017 02:12:01


Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 1GHz~3GHz




Date: 19.NOV.2017 02:35:26



Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 1GHz~3GHz






Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 1GHz~3GHz



Date: 19.NOV.2017 02:38:56

Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 1GHz~3GHz




Date: 19.NOV.2017 03:02:12



Sparton Lab.


Report No.: FR7D0728

Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 19.NOV.2017 02:39:44


Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 19.NOV.2017 03:03:01



Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 1GHz~3GHz






Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 19.NOV.2017 03:30:50


Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 19.NOV.2017 03:05:28




Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 3GHz~6GHz




Date: 22.NOV.2017 14:25:49


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 3GHz~6GHz



Date: 22.NOV.2017 14:48:59




Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 22.NOV.2017 14:26:13


Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 22.NOV.2017 14:47:43




Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 3GHz~6GHz




Date: 22 NOV. 2017 14:57:54


Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 3GHz~6GHz



Date: 22 NOV. 2017 14:53:14




Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 22.NOV.2017 14:56:22


Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 22.NOV.2017 14:54:31




Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 3GHz~6GHz



Date: 22.NOV.2017 16:10:38


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 3GHz~6GHz



Date: 22.NOV.2017 16:20:24




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 22.NOV.2017 15:14:12


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 22.NOV.2017 15:16:04




Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 3GHz~6GHz




Date: 22 NOV. 2017 16:27:30


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 3GHz~6GHz



Date: 22 NOV. 2017 16:22:59




Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 22.NOV.2017 16:26:39


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 22.NOV.2017 16:24:06




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 3GHz~6GHz




Date: 22.NOV.2017 15:30:35


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 3GHz~6GHz




Date: 22.NOV.2017 15:35:58




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 3GHz~6GHz






Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 3GHz~6GHz



Date: 17.NOV.2017 15:57:56


Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 3GHz~6GHz




Date: 17.NOV.2017 16:03:05




Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 3GHz~6GHz







Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 3GHz~6GHz







Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz







Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 3GHz~6GHz






Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 19.NOV.2017 01:48:25


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 19.NOV.2017 02:06:38




Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 3GHz~6GHz




Date: 19.NOV.2017 02:13:55


Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 3GHz~6GHz




Date: 19 NOV.2017 02:31:37




Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 3GHz~6GHz






Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 3GHz~6GHz




Date: 19.NOV.2017 02:41:39


Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 3GHz~6GHz



Date: 19.NOV.2017 02:59:39




Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 19.NOV.2017 02.43:18

Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 19.NOV.2017 03.00:22



SPARTON LAB.


Report No.: FR7D0728

Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 3GHz~6GHz




Date: 19.NOV.2017 03:26:14


Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 3GHz~6GHz



Date: 19.NOV.2017 03:06:17




Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 19.NOV.2017 03:27:58

Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 19.NOV.2017 03:07:30



Sparton Lab.


Report No.: FR7D0728

Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 6GHz~9GHz



Date: 22.NOV.2017 11:46:09


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 6GHz~9GHz



Date: 22.NOV.2017 11:21:49




Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 22.NOV.2017 11:45:35


Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 22.NOV.2017 11:21:26




Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 6GHz~9GHz




Date: 22.NOV.2017 11:46:35


Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 6GHz~9GHz



Date: 22.NOV.2017 11:22:26




Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz



Date 22.NOV.2017 11:46:13


Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz



Date 22.NOV.2017 11:22:46




Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 6GHz~9GHz



Date: 22.NOV.2017 11:47:08


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 6GHz~9GHz



Date: 22.NOV.2017 11:23:47




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 22.NOV.2017. 11:47:36


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 22.NOV.2017 11:23:30




Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 6GHz~9GHz




Date: 22.NOV.2017 11:31:48


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 6GHz~9GHz



Date: 22.NOV.2017 11:24:34




Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 22.NOV.2017 11:31:08


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 22.NOV.2017 11:25:00




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 6GHz~9GHz



Date: 22.NOV.2017 11:30:14

Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 6GHz~9GHz



Date: 22.NOV.2017 11:26:45