



Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 1GHz~3GHz






Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 3GHz~6GHz






Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 3GHz~6GHz






Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 3GHz~6GHz




Date: 21.NOV.2017 16:45:03


Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 16:10:31




Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 21.NOV.2017 16:46:00

Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 21.NOV.2017 16:10:59

Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 15:47:07


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 16:12:27




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 16:47:26


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 16:12:00




Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 | 5:48:14


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 | 5:51:42




Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 15:46:31


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 15:51:57




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 | 16:49:12


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 | 15:50:47




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 15:49:23


Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 21.NOV.2017 16:51:00




Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 3GHz~6GHz






Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 16.NOV.2017 09:48:39


Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 16.NOV.2017 09:53:55




Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 3GHz~6GHz




Date: 18.NOV.2017 10:27:19


Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 10:05:26




Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 10:28:55


Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 10:09:55




Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 10:44:00


Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 11:00:17




Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 18.NOV.2017 10:44:31


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 11:01:12




Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 3GHz~6GHz




Date: 18.NOV.2017 22:32:20


Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 23:06:21




Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 22:38:04


Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 18.NOV.2017 23:07:36



Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 3GHz~6GHz






Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 23:32:24


Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 19.NOV.2017 00:02:43




Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 3GHz~6GHz






Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 3GHz~6GHz






Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 16:29:10


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 16:24:41




Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 16:29:21


Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 16:24:17




Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 15:30:11


Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 6GHz~9GHz




Date: 21.NOV.2017 15:25:36



Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz






Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 15:30:43


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 16:26:31




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 15:30:56


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 15:26:16




Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 16:32:07


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 16:27:12




Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 16:31:28


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 16:27:24




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 15:33:06


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 6GHz~9GHz




Date: 21.NOV.2017 16:28:05



Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 6GHz~9GHz






Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:34:13


Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:11:41




Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:34:38


Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:29:50




Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:37:17


Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:08:06




Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 18.NOV.2017 11:38:06


Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:08:34




Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:40:14


Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:05:56




Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:39:08


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:06:54




Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 22:44:56


Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 23:02:11




Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 22:45:46


Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 23:02:47




Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 23:33:55


Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 23:55:01




Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 23:34:39


Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 23:55:47




Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 6GHz~9GHz



Date: 19.NOV.2017 00:17:50


Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 6GHz~9GHz



Date: 19.NOV.2017 00:41:11




Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 19.NOV.2017 00:18:39

Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 19.NOV.2017 00:42:42

Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 9GHz~18GHz




Date: 21.NOV.2017 14:35:06


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:04:37




Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 21.NOV.2017 14:35:48


Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:07:21




Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 14:37:33


Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:08:43




Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 21.NOV.2017 14:37:01


Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:08:11




Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 14:43:00


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017, 12:09:17




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 14:43:39


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 21.NOV.2017 12:08:51



Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 9GHz~18GHz






Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 12:13:13


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:10:20




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 12:12:10


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 9GHz~18GHz




Date: 21.NOV.2017 12:11:10



Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 9GHz~18GHz






Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 9GHz~18GHz




Date: 18.NOV.2017 11:59:37


Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 9GHz~18GHz



Date: 18.NOV.2017 12:23:48




Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 18.NOV.2017. 12:00:42


Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 18.NOV.2017 12:24:41



Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 9GHz~18GHz






Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 18.NOV.2017 12:05:27


Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 18.NOV.2017 12:22:37




Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 9GHz~18GHz



Date: 18.NOV.2017 12:17:15

Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 9GHz~18GHz



Date: 18.NOV.2017 12:20:23