



Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:16:08

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:16:33

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:16:48

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:17:16

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:16:58

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:17:26

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:17:45

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:18:26

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:17:56

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:18:37


Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:18:57

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:20:26

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:19:07

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:19:48

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:20:44

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:21:14

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:20:55

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:21:24

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 21:41:32

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 21:59:17


Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 00:47:27

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 00:50:32

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 00:48:31

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 00:51:04

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 00:53:08

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 00:56:31

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 00:53:55

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 00:57:29

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 00:59:31

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:02:23

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:00:28

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:03:18

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 10:56:23

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 11:32:33

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 10:57:19

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 11:32:00

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:06:29

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:08:16

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:07:14

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:09:23

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:10:20

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:11:57

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:10:58

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:12:47

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:16:00

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:17:49

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:16:51

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:18:35

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 11:50:35

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 11:46:34

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 11:50:13

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 11:46:49

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:23:11

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:23:54

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:23:23

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:24:08

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:24:44

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:25:25


Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:26:11

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:26:52

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:26:22

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:27:04


Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 18GHz~40GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:27:43

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:28:32

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:27:57

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:28:45

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:29:21

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:30:07

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:29:33

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:30:18


Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 18GHz~40GHz




Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:22:10

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:24:24

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:23:02

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:24:58

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:26:45

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:28:46

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:27:35

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:29:54

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:31:18

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:33:29

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:32:07

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:34:19

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 18GHz~40GHz



Date: 13.OCT.2017 11:28:41

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 18GHz~40GHz



Date: 13.OCT.2017 11:30:50