

Brand Name: Cambium Networks Model No.: cnPilot e502S Outdoor



Report No. : EP781425



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 22
EP Report Version : Rev. 01
Issued Date : Sep. 04, 2017








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 2 of 22
EP Report Version : Rev. 01
Issued Date : Sep. 04, 2017

Report No. : EP781425







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 22
EP Report Version : Rev. 01
Issued Date : Sep. 04, 2017

Report No. : EP781425

Cambium Networks™ MODEL NO / HVIN: C000100P502A Ashburton, TQ137UP, UK cnPilot e502S Outdoor PART NO: PL-502S000A-RW VIN: 42.5-57V --- ; IMAX: 0.7A se FCC ID: Z8H89FT0037 IC: 109W-0037 T TERMINET THE REPORT OF THE PRINT OF THE PR SERIAL NO(MSN): W8TH07F4T00V IMPORTANT
See the System User Guide
before connecting to AC
power. The guide is available online at
http://www.cambiumnetworks.com/user_guides MAC(ESN): 000456A27E42 FC (6 15 12 MADE IN CHINA 246000002121A R01



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 22 EP Report Version : Rev. 01

: Sep. 04, 2017

Issued Date

Report No.: EP781425