



Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 19:44:43

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 20:00:38

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 20:09:49

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 20:29:23

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 20:10:24

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 20:27:41


Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 22:32:43

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 22:33:39


Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 22:29:33

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 22:28:38

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 22:23:38

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 22:26:22

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 22:24:42

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 22:25:32


Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 6GHz~9GHz




Date: 16.OCT.2017 22:18:07

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 6GHz~9GHz




Date: 16.OCT.2017 22:26:58


Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 19:38:06

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 20:00:03


Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 6GHz~9GHz




Date: 16.OCT.2017 23:41:48

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 6GHz~9GHz




Date: 16.OCT.2017 23:54:22


Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 00:56:41

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 01:03:17


Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 01:16:01

Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 01:23:41


Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 20:29:46

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 20:45:52

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 18:01:51

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 19:34:00

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 18:01:32

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 19:32:46

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 19:46:01

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 19:57:00

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 19:46:20

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 19:56:34

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 20:12:27

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 20:25:39

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 20:12:45

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 20:25:23


Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 13.OCT.2017 01:25:17

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 13.OCT.2017 01:33:45

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:26:59

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 21:36:54

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:26:14

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 21:37:24

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:42:05

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 21:51:24

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:42:24

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 21:51:04

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:56:21

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 22:04:23

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:56:42

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 22:04:05

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 6GHz~9GHz




Date: 13.OCT.2017 01:25:56

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 6GHz~9GHz




Date: 13.OCT.2017 01:27:18

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 13.OCT.2017 01:26:19

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 13.OCT.2017 01:26:57

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 9GHz~18GHz




Date: 16.OCT.2017 22:19:23

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 9GHz~18GHz




Date: 16.OCT.2017 22:25:46


Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 9GHz~18GHz

