




Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.OCT.2017 11:11:21

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 11:13:40

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 20.OCT.2017 11:12:16

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 11:14:01


Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 19.OCT.2017 10:36:28

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 19.OCT.2017 10:31:28


Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 7.OCT.2017 23:26:10

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 7.OCT.2017 23:29:45


Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 3GHz~6GHz




Date: 7.OCT.2017 23:40:50

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 3GHz~6GHz




Date: 7.OCT.2017 23:43:54


Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.OCT.2017 17:06:57

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.OCT.2017 17:07:23

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 3.OCT.2017 17:07:08

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 3.OCT.2017 17:07:33

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.OCT.2017 17:07:45

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.OCT.2017 17:08:13

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 3.OCT.2017 17:07:54

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 3.OCT.2017 17:08:25

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.OCT.2017 17:09:03

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.OCT.2017 17:09:30


Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.OCT.2017 17:12:20

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.OCT.2017 17:12:44

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 3.OCT.2017 17:12:30

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 3.OCT.2017 17:12:56

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.OCT.2017 17:13:11

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.OCT.2017 17:13:38


Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 21:39:00

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 21:57:17


Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 6GHz~9GHz




Date: 19.OCT.2017 11:05:39

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 6GHz~9GHz




Date: 19.OCT.2017 11:02:51

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 19.OCT.2017 11:06:06

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 19.OCT.2017 11:02:26

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 6GHz~9GHz




Date: 19.OCT.2017 11:04:50

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 6GHz~9GHz




Date: 19.OCT.2017 11:03:21

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 19.OCT.2017 11:04:32

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 19.OCT.2017 11:03:43


Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 13.OCT.2017 10:59:09

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 13.OCT.2017 11:35:26

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 6GHz~9GHz




Date: 19.OCT.2017 11:07:38

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 6GHz~9GHz




Date: 19.OCT.2017 11:12:50

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 19.OCT.2017 11:07:58

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 19.OCT.2017 11:12:34


Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 19.OCT.2017 11:08:38

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 19.OCT.2017 11:11:52

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 6GHz~9GHz




Date: 19.OCT.2017 11:09:31

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 6GHz~9GHz




Date: 19.OCT.2017 11:10:59

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 19.OCT.2017 11:09:50

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 19.OCT.2017 11:10:35

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 6GHz~9GHz




Date: 13.OCT.2017 11:51:14

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 6GHz~9GHz




Date: 13.OCT.2017 11:45:49

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 13.OCT.2017 11:51:40

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 13.OCT.2017 11:45:27

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 9GHz~18GHz

