



Brand Name: Cambium Networks Model No.: cnPilot E501S Outdoor



**Report No. : EP721518** 



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 2 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 5 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 6 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 7 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 8 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 9 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 10 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017




PN: C000100P501A
MSN: W8TA009CS75L
ESN: 000456934ED0
2.4 GHz: 000456935080
5 GHz: 0004569356C0
NI2CA1128003E
P/N: 142000001394A
REV. C

**Report No.: EP721518** 



TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 11 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 12 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 13 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 14 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 15 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 16 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 17 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 18 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017



TOSHIBA LH4195
TAIWAN 16319 A E
TC58NVGOS3HTAIO

**Report No. : EP721518** 

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 19 of 19
EP Report Version : Rev. 04
Issued Date : Apr. 19, 2017