




**Plot on Configuration VHT80 / 5210 MHz / Average / Port 3 / 3GHz~6GHz**



Date: 31.MAR.2018 17:51:01

**Plot on Configuration VHT80 / 5210 MHz / Average / Port 4 / 3GHz~6GHz**



Date: 31.MAR.2018 18:01:43

**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 1 / 3GHz~6GHz**



Date: 31.MAR.2018 17:08:07

**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 2 / 3GHz~6GHz**




Date: 31.MAR.2018 17:31:06



**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 3 / 3GHz~6GHz**




Date: 31.MAR.2018 17:52:37



**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 4 / 3GHz~6GHz**




Date: 31.MAR.2018 18:04:15



**Plot on Configuration VHT20 / 5745 MHz / Average / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5745 MHz / Average / Port 2 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5745 MHz / Average / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5745 MHz / Average / Port 4 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5745 MHz / Peak / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5745 MHz / Peak / Port 2 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5745 MHz / Peak / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5745 MHz / Peak / Port 4 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5785 MHz / Average / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5785 MHz / Average / Port 2 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5785 MHz / Average / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5785 MHz / Average / Port 4 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5785 MHz / Peak / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5785 MHz / Peak / Port 2 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5785 MHz / Peak / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5785 MHz / Peak / Port 4 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5825 MHz / Average / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5825 MHz / Average / Port 2 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5825 MHz / Average / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5825 MHz / Average / Port 4 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5825 MHz / Peak / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5825 MHz / Peak / Port 2 / 3GHz~6GHz**




**Plot on Configuration VHT20 / 5825 MHz / Peak / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT20 / 5825 MHz / Peak / Port 4 / 3GHz~6GHz**




**Plot on Configuration VHT40 / 5755 MHz / Average / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT40 / 5755 MHz / Average / Port 2 / 3GHz~6GHz**




**Plot on Configuration VHT40 / 5755 MHz / Average / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT40 / 5755 MHz / Average / Port 4 / 3GHz~6GHz**




**Plot on Configuration VHT40 / 5755 MHz / Peak / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT40 / 5755 MHz / Peak / Port 2 / 3GHz~6GHz**




**Plot on Configuration VHT40 / 5755 MHz / Peak / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT40 / 5755 MHz / Peak / Port 4 / 3GHz~6GHz**




**Plot on Configuration VHT40 / 5795 MHz / Average / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT40 / 5795 MHz / Average / Port 2 / 3GHz~6GHz**




**Plot on Configuration VHT40 / 5795 MHz / Average / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT40 / 5795 MHz / Average / Port 4 / 3GHz~6GHz**




**Plot on Configuration VHT40 / 5795 MHz / Peak / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT40 / 5795 MHz / Peak / Port 2 / 3GHz~6GHz**



**Plot on Configuration VHT40 / 5795 MHz / Peak / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT40 / 5795 MHz / Peak / Port 4 / 3GHz~6GHz**


**Plot on Configuration VHT80 / 5775 MHz / Average / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT80 / 5775 MHz / Average / Port 2 / 3GHz~6GHz**



**Plot on Configuration VHT80 / 5775 MHz / Average / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT80 / 5775 MHz / Average / Port 4 / 3GHz~6GHz**


**Plot on Configuration VHT80 / 5775 MHz / Peak / Port 1 / 3GHz~6GHz**

**Plot on Configuration VHT80 / 5775 MHz / Peak / Port 2 / 3GHz~6GHz**



**Plot on Configuration VHT80 / 5775 MHz / Peak / Port 3 / 3GHz~6GHz**

**Plot on Configuration VHT80 / 5775 MHz / Peak / Port 4 / 3GHz~6GHz**


**Plot on Configuration VHT20 / 5180 MHz / Average / Port 1 / 6GHz~9GHz**



Date: 30.MAR.2018 16:04:21

**Plot on Configuration VHT20 / 5180 MHz / Average / Port 2 / 6GHz~9GHz**



Date: 30.MAR.2018 16:07:39

**Plot on Configuration VHT20 / 5180 MHz / Average / Port 3 / 6GHz~9GHz**



Date: 30.MAR.2018 16:15:40

**Plot on Configuration VHT20 / 5180 MHz / Average / Port 4 / 6GHz~9GHz**



Date: 30.MAR.2018 16:19:14

**Plot on Configuration VHT20 / 5180 MHz / Peak / Port 1 / 6GHz~9GHz**



Date: 30.MAR.2018 16:05:36

**Plot on Configuration VHT20 / 5180 MHz / Peak / Port 2 / 6GHz~9GHz**



Date: 30.MAR.2018 16:08:29

**Plot on Configuration VHT20 / 5180 MHz / Peak / Port 3 / 6GHz~9GHz**



Date: 30.MAR.2018 16:16:40

**Plot on Configuration VHT20 / 5180 MHz / Peak / Port 4 / 6GHz~9GHz**



Date: 30.MAR.2018 16:20:06

**Plot on Configuration VHT20 / 5200 MHz / Average / Port 1 / 6GHz~9GHz**



Date: 30.MAR.2018 16:33:56

**Plot on Configuration VHT20 / 5200 MHz / Average / Port 2 / 6GHz~9GHz**



Date: 30.MAR.2018 16:36:52

**Plot on Configuration VHT20 / 5200 MHz / Average / Port 3 / 6GHz~9GHz**



Date: 30.MAR.2018 16:47:57

**Plot on Configuration VHT20 / 5200 MHz / Average / Port 4 / 6GHz~9GHz**



Date: 30.MAR.2018 16:51:11

**Plot on Configuration VHT20 / 5200 MHz / Peak / Port 1 / 6GHz~9GHz**



Date: 30.MAR.2018 16:34:38

**Plot on Configuration VHT20 / 5200 MHz / Peak / Port 2 / 6GHz~9GHz**



Date: 30.MAR.2018 16:37:43

**Plot on Configuration VHT20 / 5200 MHz / Peak / Port 3 / 6GHz~9GHz**



Date: 30.MAR.2018 16:48:47

**Plot on Configuration VHT20 / 5200 MHz / Peak / Port 4 / 6GHz~9GHz**



Date: 30.MAR.2018 16:52:06

**Plot on Configuration VHT20 / 5240 MHz / Average / Port 1 / 6GHz~9GHz**



Date: 30.MAR.2018 17:18:35

**Plot on Configuration VHT20 / 5240 MHz / Average / Port 2 / 6GHz~9GHz**



Date: 30.MAR.2018 17:24:56

**Plot on Configuration VHT20 / 5240 MHz / Average / Port 3 / 6GHz~9GHz**



Date: 30.MAR.2018 17:48:19

**Plot on Configuration VHT20 / 5240 MHz / Average / Port 4 / 6GHz~9GHz**



Date: 30.MAR.2018 17:53:07

**Plot on Configuration VHT20 / 5240 MHz / Peak / Port 1 / 6GHz~9GHz**



Date: 30.MAR.2018 17:19:41

**Plot on Configuration VHT20 / 5240 MHz / Peak / Port 2 / 6GHz~9GHz**



Date: 30.MAR.2018 17:27:56

**Plot on Configuration VHT20 / 5240 MHz / Peak / Port 3 / 6GHz~9GHz**



Date: 30.MAR.2018 17:50:32

**Plot on Configuration VHT20 / 5240 MHz / Peak / Port 4 / 6GHz~9GHz**



Date: 30.MAR.2018 17:54:05

**Plot on Configuration VHT40 / 5190 MHz / Average / Port 1 / 6GHz~9GHz**



Date: 31.MAR.2018 15:24:17

**Plot on Configuration VHT40 / 5190 MHz / Average / Port 2 / 6GHz~9GHz**



Date: 31.MAR.2018 15:44:02

**Plot on Configuration VHT40 / 5190 MHz / Average / Port 3 / 6GHz~9GHz**



Date: 31.MAR.2018 15:40:39

**Plot on Configuration VHT40 / 5190 MHz / Average / Port 4 / 6GHz~9GHz**




Date: 31.MAR.2018 15:46:47


**Plot on Configuration VHT40 / 5190 MHz / Peak / Port 1 / 6GHz~9GHz**


Date: 31.MAR.2018 15:25:13


**Plot on Configuration VHT40 / 5190 MHz / Peak / Port 2 / 6GHz~9GHz**


Date: 31.MAR.2018 15:44:50



**Plot on Configuration VHT40 / 51980 MHz / Peak / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5190 MHz / Peak / Port 4 / 6GHz~9GHz**




**Plot on Configuration VHT40 / 5230 MHz / Average / Port 1 / 6GHz~9GHz**



Date: 31.MAR.2018 16:10:03

**Plot on Configuration VHT40 / 5230 MHz / Average / Port 2 / 6GHz~9GHz**



Date: 31.MAR.2018 16:14:04

**Plot on Configuration VHT40 / 5230 MHz / Average / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5230 MHz / Average / Port 4 / 6GHz~9GHz**



**Plot on Configuration VHT40 / 5230 MHz / Peak / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5230 MHz / Peak / Port 2 / 6GHz~9GHz**


**Plot on Configuration VHT40 / 5230 MHz / Peak / Port 3 / 6GHz~9GHz**



Date: 31.MAR.2018 16:30:51

**Plot on Configuration VHT40 / 5230 MHz / Peak / Port 4 / 6GHz~9GHz**



Date: 31.MAR.2018 16:40:49

**Plot on Configuration VHT80 / 5210 MHz / Average / Port 1 / 6GHz~9GHz**



Date: 31.MAR.2018 17:10:02

**Plot on Configuration VHT80 / 5210 MHz / Average / Port 2 / 6GHz~9GHz**



Date: 31.MAR.2018 17:25:27

**Plot on Configuration VHT80 / 5210 MHz / Average / Port 3 / 6GHz~9GHz**



Date: 31.MAR.2018 17:54:10

**Plot on Configuration VHT80 / 5210 MHz / Average / Port 4 / 6GHz~9GHz**



Date: 31.MAR.2018 17:58:09

**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 1 / 6GHz~9GHz**



Date: 31.MAR.2018 17:11:19

**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 2 / 6GHz~9GHz**




Date: 31.MAR.2018 17:27:25



**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 3 / 6GHz~9GHz**




Date: 31.MAR.2018 17:55:32



**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 4 / 6GHz~9GHz**




Date: 31.MAR.2018 17:59:00



**Plot on Configuration VHT20 / 5745 MHz / Average / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5745 MHz / Average / Port 2 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5745 MHz / Average / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5745 MHz / Average / Port 4 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5745 MHz / Peak / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5745 MHz / Peak / Port 2 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5745 MHz / Peak / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5745 MHz / Peak / Port 4 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5785 MHz / Average / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5785 MHz / Average / Port 2 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5785 MHz / Average / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5785 MHz / Average / Port 4 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5785 MHz / Peak / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5785 MHz / Peak / Port 2 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5785 MHz / Peak / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5785 MHz / Peak / Port 4 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5825 MHz / Average / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5825 MHz / Average / Port 2 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5825 MHz / Average / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5825 MHz / Average / Port 4 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5825 MHz / Peak / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5825 MHz / Peak / Port 2 / 6GHz~9GHz**




**Plot on Configuration VHT20 / 5825 MHz / Peak / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT20 / 5825 MHz / Peak / Port 4 / 6GHz~9GHz**




**Plot on Configuration VHT40 / 5755 MHz / Average / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5755 MHz / Average / Port 2 / 6GHz~9GHz**




**Plot on Configuration VHT40 / 5755 MHz / Average / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5755 MHz / Average / Port 4 / 6GHz~9GHz**




**Plot on Configuration VHT40 / 5755 MHz / Peak / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5755 MHz / Peak / Port 2 / 6GHz~9GHz**




**Plot on Configuration VHT40 / 5755 MHz / Peak / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5755 MHz / Peak / Port 4 / 6GHz~9GHz**




**Plot on Configuration VHT40 / 5795 MHz / Average / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5795 MHz / Average / Port 2 / 6GHz~9GHz**




**Plot on Configuration VHT40 / 5795 MHz / Average / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5795 MHz / Average / Port 4 / 6GHz~9GHz**




**Plot on Configuration VHT40 / 5795 MHz / Peak / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5795 MHz / Peak / Port 2 / 6GHz~9GHz**



**Plot on Configuration VHT40 / 5795 MHz / Peak / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT40 / 5795 MHz / Peak / Port 4 / 6GHz~9GHz**


**Plot on Configuration VHT80 / 5775 MHz / Average / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT80 / 5775 MHz / Average / Port 2 / 6GHz~9GHz**



**Plot on Configuration VHT80 / 5775 MHz / Average / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT80 / 5775 MHz / Average / Port 4 / 6GHz~9GHz**


**Plot on Configuration VHT80 / 5775 MHz / Peak / Port 1 / 6GHz~9GHz**

**Plot on Configuration VHT80 / 5775 MHz / Peak / Port 2 / 6GHz~9GHz**



**Plot on Configuration VHT80 / 5775 MHz / Peak / Port 3 / 6GHz~9GHz**

**Plot on Configuration VHT80 / 5775 MHz / Peak / Port 4 / 6GHz~9GHz**


**Plot on Configuration VHT20 / 5180 MHz / Average / Port 1 / 9GHz~18GHz**



Date: 31.MAR.2018 18:22:31

**Plot on Configuration VHT20 / 5180 MHz / Average / Port 2 / 9GHz~18GHz**



Date: 31.MAR.2018 18:32:47

**Plot on Configuration VHT20 / 5180 MHz / Average / Port 3 / 9GHz~18GHz**



Date: 31.MAR.2018 18:35:45

**Plot on Configuration VHT20 / 5180 MHz / Average / Port 4 / 9GHz~18GHz**



Date: 31.MAR.2018 18:45:09

**Plot on Configuration VHT20 / 5180 MHz / Peak / Port 1 / 9GHz~18GHz**



Date: 31.MAR.2018 18:23:25

**Plot on Configuration VHT20 / 5180 MHz / Peak / Port 2 / 9GHz~18GHz**



Date: 31.MAR.2018 18:33:43

**Plot on Configuration VHT20 / 5180 MHz / Peak / Port 3 / 9GHz~18GHz**



Date: 31.MAR.2018 18:36:42

**Plot on Configuration VHT20 / 5180 MHz / Peak / Port 4 / 9GHz~18GHz**



Date: 31.MAR.2018 18:46:01

**Plot on Configuration VHT20 / 5200 MHz / Average / Port 1 / 9GHz~18GHz**



Date: 31.MAR.2018 18:53:05

**Plot on Configuration VHT20 / 5200 MHz / Average / Port 2 / 9GHz~18GHz**



Date: 31.MAR.2018 19:04:42

**Plot on Configuration VHT20 / 5200 MHz / Average / Port 3 / 9GHz~18GHz**



Date: 31.MAR.2018 19:08:03

**Plot on Configuration VHT20 / 5200 MHz / Average / Port 4 / 9GHz~18GHz**




Date: 31.MAR.2018 19:19:14


**Plot on Configuration VHT20 / 5200 MHz / Peak / Port 1 / 9GHz~18GHz**


Date: 31.MAR.2018 18:54:06


**Plot on Configuration VHT20 / 5200 MHz / Peak / Port 2 / 9GHz~18GHz**


Date: 31.MAR.2018 19:05:46


**Plot on Configuration VHT20 / 5200 MHz / Peak / Port 3 / 9GHz~18GHz**

**Plot on Configuration VHT20 / 5200 MHz / Peak / Port 4 / 9GHz~18GHz**


**Plot on Configuration VHT20 / 5240 MHz / Average / Port 1 / 9GHz~18GHz**



Date: 31.MAR.2018 19:24:42

**Plot on Configuration VHT20 / 5240 MHz / Average / Port 2 / 9GHz~18GHz**




Date: 31.MAR.2018 19:35:40



**Plot on Configuration VHT20 / 5240 MHz / Average / Port 3 / 9GHz~18GHz**



Date: 31.MAR.2018 19:40:39

**Plot on Configuration VHT20 / 5240 MHz / Average / Port 4 / 9GHz~18GHz**



Date: 31.MAR.2018 19:52:34

**Plot on Configuration VHT20 / 5240 MHz / Peak / Port 1 / 9GHz~18GHz**

**Plot on Configuration VHT20 / 5240 MHz / Peak / Port 2 / 9GHz~18GHz**



**Plot on Configuration VHT20 / 5240 MHz / Peak / Port 3 / 9GHz~18GHz**

**Plot on Configuration VHT20 / 5240 MHz / Peak / Port 4 / 9GHz~18GHz**


**Plot on Configuration VHT40 / 5190 MHz / Average / Port 1 / 9GHz~18GHz**



Date: 31.MAR.2018 20:01:31

**Plot on Configuration VHT40 / 5190 MHz / Average / Port 2 / 9GHz~18GHz**




Date: 31.MAR.2018 20:14:31



**Plot on Configuration VHT40 / 5190 MHz / Average / Port 3 / 9GHz~18GHz**



Date: 31.MAR.2018 20:18:48

**Plot on Configuration VHT40 / 5190 MHz / Average / Port 4 / 9GHz~18GHz**



Date: 31.MAR.2018 20:29:15

**Plot on Configuration VHT40 / 5190 MHz / Peak / Port 1 / 9GHz~18GHz**

**Plot on Configuration VHT40 / 5190 MHz / Peak / Port 2 / 9GHz~18GHz**



**Plot on Configuration VHT40 / 5190 MHz / Peak / Port 3 / 9GHz~18GHz**

**Plot on Configuration VHT40 / 5190 MHz / Peak / Port 4 / 9GHz~18GHz**


**Plot on Configuration VHT40 / 5230 MHz / Average / Port 1 / 9GHz~18GHz**



Date: 31.MAR.2018 20:55:28

**Plot on Configuration VHT40 / 5230 MHz / Average / Port 2 / 9GHz~18GHz**




Date: 31.MAR.2018 21:05:52


**Plot on Configuration VHT40 / 5230 MHz / Average / Port 3 / 9GHz~18GHz**


Date: 31.MAR.2018 21:09:50


**Plot on Configuration VHT40 / 5230 MHz / Average / Port 4 / 9GHz~18GHz**


Date: 31.MAR.2018 21:21:21


**Plot on Configuration VHT40 / 5230 MHz / Peak / Port 1 / 9GHz~18GHz**

**Plot on Configuration VHT40 / 5230 MHz / Peak / Port 2 / 9GHz~18GHz**


**Plot on Configuration VHT40 / 5230 MHz / Peak / Port 3 / 9GHz~18GHz**



Date: 31.MAR.2018 21:10:35

**Plot on Configuration VHT40 / 5230 MHz / Peak / Port 4 / 9GHz~18GHz**



Date: 31.MAR.2018 21:23:10

**Plot on Configuration VHT80 / 5210 MHz / Average / Port 1 / 9GHz~18GHz**



Date: 31.MAR.2018 21:28:02

**Plot on Configuration VHT80 / 5210 MHz / Average / Port 2 / 9GHz~18GHz**




Date: 31.MAR.2018 21:39:10


**Plot on Configuration VHT80 / 5210 MHz / Average / Port 3 / 9GHz~18GHz**


Date: 31.MAR.2018 21:45:44


**Plot on Configuration VHT80 / 5210 MHz / Average / Port 4 / 9GHz~18GHz**


Date: 31.MAR.2018 22:04:18


**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 1 / 9GHz~18GHz**

**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 2 / 9GHz~18GHz**


**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 3 / 9GHz~18GHz**


Date: 31.MAR.2018 21:46:54

**Plot on Configuration VHT80 / 5210 MHz / Peak / Port 4 / 9GHz~18GHz**


Date: 31.MAR.2018 22:05:53

**Plot on Configuration VHT20 / 5745 MHz / Average / Port 1 / 9GHz~18GHz**

**Plot on Configuration VHT20 / 5745 MHz / Average / Port 2 / 9GHz~18GHz**
