




### Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 9GHz~18GHz




### Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 9GHz~18GHz




### Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 9GHz~18GHz




### Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 9GHz~18GHz



### Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 16.OCT.2017 23:45:07

### Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 16.OCT.2017 23:52:20


### Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




### Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




### Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 1 / 9GHz~18GHz



### Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 01:17:31

### Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 01:22:19

### Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 20:31:02

### Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 20:47:04


### Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 9GHz~18GHz




### Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 9GHz~18GHz



### Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 18:02:49

### Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 19:29:00


### Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 9GHz~18GHz



### Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 19:48:01

### Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 19:53:44

### Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 20:14:38

### Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 20:23:26

### Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 20:15:19

### Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 20:22:37

### Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 01:35:33

### Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 01:39:08

### Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 01:35:47

### Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 01:39:27

### Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:27:22

### Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 21:35:22

### Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:27:38

### Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 21:33:47

### Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:44:05

### Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 21:49:52

### Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:44:32

### Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 21:49:26

### Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:58:02

### Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 22:03:35

### Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:58:18

### Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 22:02:59

### Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 01:36:55

### Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 01:38:15

### Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 01:37:15

### Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 01:37:50

### Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 18GHz~40GHz




Date: 16.OCT.2017 22:21:29

### Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 18GHz~40GHz




Date: 16.OCT.2017 22:24:07


### Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 18GHz~40GHz



### Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 16.OCT.2017 23:46:24

### Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 16.OCT.2017 23:51:13

### Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 00:59:06

### Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 01:00:46


### Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz




### Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 1 / 18GHz~40GHz




### Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 2 / 18GHz~40GHz



### Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 1 / 18GHz~40GHz




### Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 2 / 18GHz~40GHz







Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK 80M / 5250 MHz / Average / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 20:35:38

### Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 20:50:23

### Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 18:05:13

### Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 19:25:53

### Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 18:05:48

### Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 19:11:10


### Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 18GHz~40GHz



### Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 19:49:13

### Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 19:51:55

### Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 20:17:26

### Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 20:20:19

### Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 20:16:24

### Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 20:20:49

### Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 18GHz~40GHz



Date: 13.OCT.2017 01:45:57

### Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 18GHz~40GHz



Date: 13.OCT.2017 01:51:15