





Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 22.NOV:2017 11:30:40

Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 22.NOV,2017 11:25:26

FCC ID: Z8H89FT0017


Page No.

: 162 of 377






Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 6GHz~9GHz



Date: 17.NOV.2017 16:40:43


Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 6GHz~9GHz



Date: 17,NOV.2017 16:33:29


Page No. : 163 c

: 163 of 377






Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 17.NOV.2017 16:39:40

Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 17.NOV.2017 16:35:20

FCC ID: Z8H89FT0017


Page No. : 1

: 164 of 377






Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 6GHz~9GHz




Date; 19.NOV,2017 01;21:04

Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 6GHz~9GHz




Date: 19.NOV.2017 01:35:38

Page No. : 165 of 377






Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 19.NOV.2017 01;21:45


Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 19.NOV.2017 01:21:45


FCC ID; Z8H89FT0017

Page No. : 166 of 377






Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 6GHz~9GHz



Date: 19.NOV,2017 01:50:18


Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 6GHz~9GHz



Date: 19.NOV.2017 02.03:46


Page No.

: 167 of 377






Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 19.NOV,2017 01:50:51

Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 19.NOV.2017 02.04:27

FCC ID: Z8H89FT0017


Page No.

: 168 of 377






Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 6GHz \sim 9GHz




Date: 19:NOV:2017 02:16:15

Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 6GHz~9GHz




Date: 19.NOV.2017 .02:29:52

Page No. : 169 of 377






Plot on Configuration QPSK, $80M / 5765 MHz / Peak / Port 1 / 6GHz \sim 9GHz$



Date: 19.NOV,2017 02:16:57


Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 19.NOV.2017 02:30:38


FCC ID: Z8H89FT0017

Page No. : 170 of 377






Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 6GHz~9GHz




Date, 19.NOV.2017 02.45:14

Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 6GHz~9GHz




Date: 19.NOV.2017 02;58:32

Page No. : 171 of 377






Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 19.NOV.2017.02;45:51

Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 19.NOV.2017 .02,57:31

FCC ID: Z8H89FT0017


Page No.

: 172 of 377






Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 6GHz~9GHz



Date: 19.NOV.2017 03:23:59


Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 6GHz~9GHz



Date: 19.NOV.2017 03,09:02


Page No.

: 173 of 377






Plot on Configuration QPSK, $80M / 5805 \text{ MHz} / \text{Peak} / \text{Port } 1 / 6\text{GHz} \sim 9\text{GHz}$



Date: 19,NOV:2017 03:25:04

Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 19.NOV.2017, 03:10:00

FCC ID: Z8H89FT0017


Page No.

: 174 of 377






Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 9GHz~18GHz



Date: 22.NOV.2017 11:59:45


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 9GHz \sim 18GHz



Date: 22.NOV.2017 12.09.01


Page No.

: 175 of 377






Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 22.NOV.2017, 12.00:04

Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 22.NOV.2017 12.08:15

FCC ID: Z8H89FT0017


Page No.

: 176 of 377






Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 9GHz~18GHz



Date: 22 NOV.2017 12.01:11


Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 9GHz~18GHz



Date: 22.NOV.2017 12.09:57


Page No.

: 177 of 377






Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 22.NOV.2017 12.00:30

Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 22 NOV.2017 12:10:35

FCC ID: Z8H89FT0017


Page No.

: 178 of 377






Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 9GHz~18GHz



Date: 22.NOV.2017 12.01:48


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 9GHz~18GHz



Date: 22.NOV.2017 12:11:29


Page No. : 179

: 179 of 377






Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 22 NOV 2017 12.02.06

Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 22.NOV.2017 12:11:05

FCC ID: Z8H89FT0017


Page No.

: 180 of 377






Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 9GHz~18GHz




Date: 22.NOV.2017 12.03.09

Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 9GHz \sim 18GHz




Date: 22.NOV.2017 12.07:20

Page No. : 181 of 377






Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 22 NOV.2017 12.02:47

Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 22.NOV.2017 12:07:43

FCC ID: Z8H89FT0017


Page No.

: 182 of 377






Plot on Configuration QPSK, $80M / 5210 \ MHz / Average / Port 1 / 9GHz \sim 18GHz$



Date: 22.NOV.2017 12.03:38


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 9GHz~18GHz



Date: 22 NOV.2017 12:05:50


Page No. : 18

: 183 of 377






Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 22.NOV:2017 12:03:53

Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 22.NOV.2017 12.05:17

FCC ID: Z8H89FT0017


Page No.

: 184 of 377






Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 9GHz~18GHz



Date: 17,NOV.2017, 18:57:30


Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 9GHz~18GHz



Date: 17,NOV.2017 17,00:36


FCC ID: Z8H89FT0017

Page No. : 185 of 377






Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 17.NOV.2017, 16:58:37

Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 17,NOV.2017 17;01:20

FCC ID: Z8H89FT0017


Page No.

: 186 of 377






Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 9GHz~18GHz




Date: 19.NOV.2017 01;22;44

Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 9GHz \sim 18GHz




Date: 19.NOV.2017 01:33:10

Page No. : 187 of 377






Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 19.NOV.2017 01:23:58


Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 19.NOV.2017 01:34.00


Page No.

: 188 of 377






Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 9GHz~18GHz



Date: 19.NOV.2017 01:53:00


Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 9GHz~18GHz



Date: 19.NOV.2017 .02.01:44


FCC ID: Z8H89FT0017

Page No. : 189 of 377






Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 19:NOV.2017 01:53:44

Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 19.NOV.2017 02.02.42






Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 9GHz~18GHz



Date: 19 NOV.2017 02:17:58


Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 9GHz~18GHz



Date: 19.NOV.2017 02.28.11


Page No. : 191 of 377

FCC ID: Z8H89FT0017






Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 19.NOV,2017 .02;18:30

Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 19:NOV.2017 02:27:03

FCC ID: Z8H89FT0017


Page No.

: 192 of 377






Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 9GHz~18GHz



Date: 19.NOV:2017 02:47:01


Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 9GHz \sim 18GHz



Date: 19.NOV.2017 02.54.38


Page No.

: 193 of 377






Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 19.NOV:2017 02.47:51

Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 19:NOV.2017 .02,55:40

Page No. : 194 of 377






Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 9GHz~18GHz



Date: 19.NOV.2017 03:18:52

Plot on Configuration QPSK, $80M / 5805 \text{ MHz} / \text{Average} / \text{Port 2} / 9\text{GHz} \sim 18\text{GHz}$




Date: 19.NOV.2017 03:11:05

Page No.


: 195 of 377

FCC ID: Z8H89FT0017






Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 19:NOV.2017 03:19:35

Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 19:NOV.2017 03:12:40

FCC ID: Z8H89FT0017


Page No.

: 196 of 377






Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 18GHz~40GHz



Date: 22.NOV.2017 14:14:05


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 18GHz~40GHz



Date: 22.NOV.2017 14:03:39


Page No. :

: 197 of 377






Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 22.NOV.2017 14:13:17

Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 22 NOV 2017 14 04:05

FCC ID; Z8H89FT0017


Page No.

: 198 of 377






Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 18GHz~40GHz



Date: 22.NOV.2017 14:14:49


Piot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / $18 GHz \sim 40 GHz$



Date: 22 NOV.2017 14:05:06


FCC ID: Z8H89FT0017

Page No. : 199 of 377






Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 22.NOV:2017 14:15:11

Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 22.NOV.2017 14.04:30

Page No.

: 200 of 377