



### Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 13.OCT.2017 01:46:12

### Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 13.OCT.2017 01:49:32

### Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 21:29:24

### Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 21:32:35

### Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 21:28:37

### Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 21:33:01


### Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 18GHz~40GHz



### Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 21:45:19

### Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 21:48:28

### Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 22:00:16

### Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 22:01:54

### Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 21:59:21

### Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 22:02:08

### Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 18GHz~40GHz




Date: 13.OCT.2017 01:47:30

### Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 18GHz~40GHz




Date: 13.OCT.2017 01:48:33

### Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 13.OCT.2017 01:46:52


### Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 13.OCT.2017 01:48:48

**For Antenna 2:**


**Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 1GHz~3GHz**



**Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 1GHz~3GHz**




### Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 3.OCT.2017 16:57:47

### Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 3.OCT.2017 16:58:30

### Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 1GHz~3GHz




Date: 3.OCT.2017 16:58:53

### Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 1GHz~3GHz




Date: 3.OCT.2017 16:59:21

### Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 3.OCT.2017 16:59:05

### Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 3.OCT.2017 17:00:06

### Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 1GHz~3GHz




Date: 3.OCT.2017 17:00:41

### Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 1GHz~3GHz




Date: 3.OCT.2017 17:01:16

### Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 3.OCT.2017 17:00:59

### Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 3.OCT.2017 17:01:33

### Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 1GHz~3GHz




Date: 17.OCT.2017 21:01:11

### Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 1GHz~3GHz




Date: 17.OCT.2017 21:15:28


### Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 1GHz~3GHz



### Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 1GHz~3GHz




### Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 1GHz~3GHz




Date: 3.OCT.2017 17:01:52

### Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 1GHz~3GHz




Date: 3.OCT.2017 17:02:27

### Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 3.OCT.2017 17:02:04

### Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 3.OCT.2017 17:02:36


### Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 1GHz~3GHz



### Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 1GHz~3GHz




### Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 3.OCT.2017 17:03:18

### Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 3.OCT.2017 17:03:48

### Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 1GHz~3GHz




Date: 17.OCT.2017 21:32:03

### Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 1GHz~3GHz




Date: 17.OCT.2017 21:48:50


### Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 1GHz~3GHz



### Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 1GHz~3GHz




### Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 1GHz~3GHz




Date: 7.OCT.2017 21:52:22

### Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 1GHz~3GHz




Date: 7.OCT.2017 22:01:00

### Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 7.OCT.2017 21:58:48

### Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 7.OCT.2017 22:01:54

### Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 1GHz~3GHz




Date: 7.OCT.2017 22:07:24

### Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 1GHz~3GHz




Date: 7.OCT.2017 22:04:07

### Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 7.OCT.2017 22:12:08

### Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 7.OCT.2017 22:05:37

### Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 1GHz~3GHz




Date: 7.OCT.2017 22:13:57

### Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 1GHz~3GHz




Date: 7.OCT.2017 22:18:40

### Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 7.OCT.2017 22:15:12

### Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 7.OCT.2017 22:17:26

### Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 1GHz~3GHz




Date: 13.OCT.2017 11:24:13

### Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 1GHz~3GHz




Date: 13.OCT.2017 11:42:17

### Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 13.OCT.2017 11:25:03

### Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 13.OCT.2017 11:41:58


### Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 1GHz~3GHz



### Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 1GHz~3GHz




### Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 7.OCT.2017 22:22:57

### Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 7.OCT.2017 22:25:12

### Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 1GHz~3GHz




Date: 7.OCT.2017 22:27:31

### Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 1GHz~3GHz




Date: 7.OCT.2017 22:32:26

### Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 7.OCT.2017 22:28:32

### Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 7.OCT.2017 22:33:20

### Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 1GHz~3GHz




Date: 7.OCT.2017 22:36:14

### Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 1GHz~3GHz




Date: 7.OCT.2017 22:40:59


### Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 1GHz~3GHz



### Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 1GHz~3GHz




### Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 1GHz~3GHz




Date: 13.OCT.2017 11:59:02

### Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 1GHz~3GHz




Date: 13.OCT.2017 11:43:23

### Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 13.OCT.2017 11:58:44

### Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 13.OCT.2017 11:43:33


### Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 3GHz~6GHz



### Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 3GHz~6GHz




### Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 20.OCT.2017 10:52:08

### Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 10:42:04

### Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.OCT.2017 10:54:19

### Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 10:57:04

### Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 20.OCT.2017 10:54:42

### Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 10:56:38

### Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.OCT.2017 10:59:56

### Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 10:57:56

### Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 20.OCT.2017 10:59:04

### Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 10:58:24

### Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.OCT.2017 11:23:22

### Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 11:17:56

### Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 20.OCT.2017 11:24:06

### Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 11:18:44


### Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 3GHz~6GHz



### Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 3GHz~6GHz




### Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 20.OCT.2017 11:03:05

### Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 11:04:46

### Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 3GHz~6GHz



Date: 20.OCT.2017 11:07:38

### Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 3GHz~6GHz



Date: 20.OCT.2017 11:06:06