





Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 1 / 6GHz~9GHz



Date: 22.JAN.2018 23:58:34

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 2 / 6GHz~9GHz




Date: 23.JAN.2018 00:08:13



RSE TX above 1GHz Result


Appendix E.2

Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 22.JAN.2018 23:58:13


Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 2 / 6GHz~9GHz





Date: 23.JAN.2018 00:08:30

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 1 / 9GHz~18GHz


Date: 18.JAN.2018 21:13:18


Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 2 / 9GHz~18GHz


Date: 18.JAN.2018 20:48:48

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 1 / 9GHz~18GHz

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 2 / 9GHz~18GHz





Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 1 / 9GHz~18GHz




Date: 18.JAN.2018 21:09:50


Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 2 / 9GHz~18GHz



Date: 18.JAN.2018 21:08:36

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 18.JAN.2018 21:09:34

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 2 / 9GHz~18GHz


Date: 18.JAN.2018 21:08:54




Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 1 / 9GHz~18GHz




Date: 18.JAN.2018 19:01:58


Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 2 / 9GHz~18GHz



Date: 18.JAN.2018 19:07:32

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 1 / 9GHz~18GHz


Date: 18.JAN.2018 19:02:21

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 2 / 9GHz~18GHz


Date: 18.JAN.2018 19:07:13




Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 1 / 9GHz~18GHz



Date: 18.JAN.2018 21:19:00


Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 2 / 9GHz~18GHz



Date: 18.JAN.2018 21:20:20




Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 18.JAN.2018 21:18:34


Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 18.JAN.2018 21:20:41




Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 1 / 9GHz~18GHz



Date: 18.JAN.2018 21:29:46


Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 2 / 9GHz~18GHz



Date: 18.JAN.2018 21:25:31




Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 18.JAN.2018 21:30:00


Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 18.JAN.2018 21:25:15




Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 1 / 9GHz~18GHz



Date: 18.JAN.2018 21:45:58


Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 2 / 9GHz~18GHz



Date: 18.JAN.2018 21:46:34




Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 18.JAN.2018 21:37:46


Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 18.JAN.2018 21:46:49

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 1 / 18GHz~40GHz


Date: 18.JAN.2018 21:14:23

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 2 / 18GHz~40GHz



Date: 18.JAN.2018 20:50:16



RSE TX above 1GHz Result


Appendix E.2

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 18.JAN.2018 21:13:52


Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 2 / 18GHz~40GHz





Date: 18.JAN.2018 20:49:40


Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 1 / 18GHz~40GHz


Date: 18.JAN.2018 21:06:32


Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 2 / 18GHz~40GHz


Date: 18.JAN.2018 21:08:13


Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 1 / 18GHz~40GHz

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 2 / 18GHz~40GHz


Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 1 / 18GHz~40GHz



Date: 18.JAN.2018 19:03:21

Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 2 / 18GHz~40GHz


Date: 18.JAN.2018 19:06:25

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 1 / 18GHz~40GHz


Date: 18.JAN.2018 19:02:46

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 18.JAN.2018 19:06:41



RSE TX above 1GHz Result


Appendix E.2

Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 1 / 18GHz~40GHz



Date: 18.JAN.2018 21:17:50


Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 2 / 18GHz~40GHz



Date: 18.JAN.2018 21:21:37




Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 18.JAN.2018 21:18:08


Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 18.JAN.2018 21:21:04



Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 1 / 18GHz~40GHz




Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 2 / 18GHz~40GHz






Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 18.JAN.2018 21:30:25


Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 18.JAN.2018 21:23:41

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 1 / 18GHz~40GHz



Date: 18.JAN.2018 21:35:30

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 2 / 18GHz~40GHz


Date: 18.JAN.2018 21:47:34




Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 18.JAN.2018 21:35:53


Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 18.JAN.2018 21:47:05

For Antenna 2:
Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 1 / 1GHz~3GHz

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 2 / 1GHz~3GHz


Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 19.JAN.2018 15:48:23

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 19.JAN.2018 15:39:55




Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 2 / 1GHz~3GHz



Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 19.JAN.2018 16:13:49

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 19.JAN.2018 16:56:05



Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 2 / 1GHz~3GHz






Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 2 / 1GHz~3GHz






Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 2 / 1GHz~3GHz






Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 2 / 1GHz~3GHz









Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 2 / 1GHz~3GHz



Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 1 / 1GHz~3GHz

Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 2 / 1GHz~3GHz


Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 1 / 1GHz~3GHz



Date: 19.JAN.2018 20:55:09

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 2 / 1GHz~3GHz



Date: 19.JAN.2018 20:22:44



Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 2 / 1GHz~3GHz






Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 2 / 3GHz~6GHz






RSE TX above 1GHz Result


Appendix E.2

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 19.JAN.2018 15:29:44

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 19.JAN.2018 15:35:03



Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 2 / 3GHz~6GHz






RSE TX above 1GHz Result


Appendix E.2

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 19.JAN.2018 16:24:38


Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 19.JAN.2018 16:53:12

Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 1 / 3GHz~6GHz

Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 2 / 3GHz~6GHz


Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 1 / 3GHz~6GHz


Date: 19.JAN.2018 17:09:01

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 2 / 3GHz~6GHz


Date: 19.JAN.2018 17:55:40



RSE TX above 1GHz Result

Appendix E.2

Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 1 / 3GHz~6GHz



Date: 19.JAN.2018 19:39:23


Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 2 / 3GHz~6GHz



Date: 19.JAN.2018 19:40:28




Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 19.JAN.2018 19:38:48


Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 19.JAN.2018 19:41:18

Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 1 / 3GHz~6GHz



Date: 19.JAN.2018 20:08:48

Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 2 / 3GHz~6GHz



Date: 19.JAN.2018 20:10:53



Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz






Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 1 / 3GHz~6GHz



Date: 19.JAN.2018 20:37:23

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 2 / 3GHz~6GHz




Date: 19.JAN.2018 20:29:58



RSE TX above 1GHz Result

Appendix E.2

Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 2 / 3GHz~6GHz

