

Report No.: FA181603

Appendix D. Product Photos




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z8TIU9067LS001 Page Number : D1 of D1
Report Issued Date : Dec. 19, 2011
Report Version : Rev. 01



Report No.: FA181603

Appendix E. Test Setup Photos



Face of the DUT with Phantom 0 cm Gap



Bottom of the DUT with Phantom 0 Gap



Left Side of the DUT with Phantom 0 cm Gap



Right Side of the DUT with Phantom 0 Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: Z8TIU9067LS001 Page Number : E1 of E1
Report Issued Date : Dec. 19, 2011
Report Version : Rev. 01