Internal photographs of equipment under test Top of Transmitter module without shield in place



Bottom side of Transmitter module



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

8devices


Model: Carambola WiFi module

Test #: 111127


Test to: CFR47 (15.247) File: IntPho CM1 SN: ENG1 FCC ID#: Z9W-CM1 Date: November 27, 2011

Page 1 of 4

Top of Transmitter module without shield in place



Bottom side of Transmitter module



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

8devices

Model: Carambola WiFi module

Test #: 111127


Test to: CFR47 (15.247) File: IntPho CM1


SN: ENG1

FCC ID#: Z9W-CM1 Date: November 27, 2011

Page 2 of 4

support interface boards





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-321

Phone/Fax: (913) 837-3214 Revision 1 8devices

Model: Carambola WiFi module


Test #: 111127

Test to: CFR47 (15.247) File: IntPho CM1 SN: ENG1

FCC ID#: Z9W-CM1 Date: November 27, 2011

Page 3 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

8devices

Model: Carambola WiFi module

Test #: 111127

Test to: CFR47 (15.247) File: IntPho CM1 SN: ENG1 FCC ID#: Z9W-CM1 Date: November 27, 2011

Page 4 of 4