

# Annex 3: External photographs to TEST REPORT

No.: 17-1-0047301T11a

According to: FCC Regulations
Part 15.109, Class B


IC-Regulations RSS-Gen, Issue 4 ICES-003, Issue 6

for

#### Husqvarna AB

#### Fleet Machine Sensor (FMS)

FCC-ID: ZAS-FMS2 IC:23307-FMS2 PMN: Fleet Machine Sensor HVIN: P1.2 B





### **Table of contents**

I. EXTERNAL PHOTOGRAPHS	3
1.1. Equipment Under Test (EUT)	3
1.2 Accessories	4



## 1. External photographs

#### 1.1. Equipment Under Test (EUT)




Photograph 1: Top side view, plastic top housing removed



Photograph 2: Top side view, complete housing removed



#### 1.2. Accessories



Photograph 3: Jig Board