

Annex 2: Internal photographs to TEST REPORT No.: 17-1-0047301T11a

According to: FCC Regulations
Part 15.109, Class B


IC-Regulations RSS-Gen, Issue 4 ICES-003, Issue 6


for

Husqvarna AB

Fleet Machine Sensor (FMS)

FCC-ID: ZAS-FMS2 IC:23307-FMS2 PMN: Fleet Machine Sensor HVIN: P1.2 B









1. Internal photographs

