## Fij 富多实业国际有限公司 FRUTO INDUSTRIAL INTERNATIONAL LIMITED

UNIT 1921, 19/F, CHINA SHINE PLAZE, 3-15 LIN HE XI ROAD, TIANHE DISTRICT, GUANGZHOU, CHINA

Date:2014-8-29

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

Subject: FCC Class II Permission change for FCC ID: ZBNC18-20

Original Grant Date: 2011-03-07

Dear Sir/Madam,

This is to request a Class II permission change to our Induction cooktop, Model C18-20 (FCC ID: ZBNC18-20), the device is identical to the previously certified except for the changes as below for details;

Part	Original	New
	YLS-EF PCB	EG PCB
MAIN PCB	without sheet-contact process	sheet-contact process
	MKP-X2 at C16 site	MKP-X2 at C4 site
	Chokes at L3 site	Chokes at L2 site
Control PCB	Control winding is 4 needles	Control winding is 6 needles
Thermal Fuse	without Thermal Fuse	Added Thermal Fuse

Compare to original C18-20, new model is C18-20 with MAIN PCB, control PCB changed and add the thermal fuse.

Sincerely Yours,

Typed or Printed Name: April Chan

Title: Manager