

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZBW-MPHMB001A Page Number : D1 of D3
Report Issued Date : Jun. 28, 2016
Report Version : Rev. 01

Report No.: FR640601C


Report Template No.: BU5-FR15CWL Version 1.3




<Radiated Emission>

Z Plane for 802.11b/g

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZBW-MPHMB001A Page Number : D2 of D3
Report Issued Date : Jun. 28, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR640601C


Report No.: FR640601C

X Plane for 802.11 n HT20

LF



 ${\sf HF}$



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZBW-MPHMB001A Page Number : D3 of D3
Report Issued Date : Jun. 28, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.3