

# Appendix D. Setup Photographs

## <Conducted Emission>

#### Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZBW-MPHMB001A Page Number : D1 of D2
Report Issued Date : Jun. 28, 2016
Report Version : Rev. 01

Report No.: FR640601B


Report Template No.: BU5-FR15CBT4.0 Version 1.3

# C RF Test Report No. : FR640601B


### <Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZBW-MPHMB001A Page Number : D2 of D2
Report Issued Date : Jun. 28, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 1.3