Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZC4W250 Page Number : B1 of B2 Report Issued Date : Feb. 09, 2015

Report No.: FR4D1704B


Report Version : Rev. 01




<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZC4W250 Page Number : B2 of B2 Report Issued Date : Feb. 09, 2015

Report No.: FR4D1704B

Report Version : Rev. 01