

Report No. : FA370202

## Appendix D. **Test Setup Photos**





Right Cheek

**Right Tilted** 





**Left Tilted** Left Cheek

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZC4S105

Page Number : D1 of D2 Report Issued Date: Jul. 23, 2013

Report Version : Rev. 01








Report No. : FA370202

Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap







Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZC4S105

Page Number : D2 of D2 Report Issued Date: Jul. 23, 2013 Report Version : Rev. 01