

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZC4X700 Page Number : B1 of B3
Report Issued Date : Mar. 12, 2015
Report Version : Rev. 01


Report No.: FR511905C



<Radiated Emission>

Z Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZC4X700 Page Number : B2 of B3
Report Issued Date : Mar. 12, 2015
Report Version : Rev. 01


Report No.: FR511905C





Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZC4X700 Page Number : B3 of B3
Report Issued Date : Mar. 12, 2015
Report Version : Rev. 01

Report No.: FR511905C