## 3. Internal Photograph of EUT

Brand Name: LANIX; Model Name: Ilium S105

Report No.: EP370202



TEL: 86-755-3320-2398 FCC ID: ZC4S105 Page Number : 11 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01

Report No.: EP370202



TEL: 86-755-3320-2398 FCC ID: ZC4S105 Page Number : 12 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01

Brand Name: LANIX; Model Name: Ilium S105



TEL: 86-755-3320-2398 FCC ID: ZC4S105 Page Number : 13 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01




Report No.: EP370202



TEL: 86-755-3320-2398 FCC ID: ZC4S105


Page Number : 14 of 26 Report Issued Date : Jul. 23, 2013 Report Version : Rev. 01

Report No.: EP370202




TEL: 86-755- 3320-2398 FCC ID: ZC4S105

Page Number : 15 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01




TEL: 86-755-3320-2398 FCC ID: ZC4S105 Page Number : 16 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01

Report No.: EP370202




TEL: 86-755-3320-2398 FCC ID: ZC4S105 Page Number : 17 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01

Brand Name: LANIX; Model Name: Ilium S105




TEL: 86-755-3320-2398 FCC ID: ZC4S105 Page Number : 18 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: ZC4S105 Page Number : 19 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01

Report No.: EP370202



TEL: 86-755- 3320-2398 FCC ID: ZC4S105

Page Number : 20 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01


Report No.: EP370202



TEL: 86-755- 3320-2398 FCC ID: ZC4S105

Page Number : 21 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01


Report No.: EP370202



TEL: 86-755- 3320-2398 FCC ID: ZC4S105

Page Number : 22 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01


Report No.: EP370202



TEL: 86-755- 3320-2398 FCC ID: ZC4S105

Page Number : 23 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01

Report No.: EP370202



TEL: 86-755-3320-2398 FCC ID: ZC4S105 Page Number : 24 of 26 Report Issued Date : Jul. 23, 2013 Report Version : Rev. 01

Report No.: EP370202



TEL: 86-755-3320-2398 FCC ID: ZC4S105 Page Number : 25 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01

Report No.: EP370202



TEL: 86-755-3320-2398 FCC ID: ZC4S105 Page Number : 26 of 26
Report Issued Date : Jul. 23, 2013
Report Version : Rev. 01