Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZC4X700 Page Number : B1 of B2
Report Issued Date : Mar. 12, 2015


Report No.: FR511905B

Report Version : Rev. 01


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZC4X700 Page Number : B2 of B2
Report Issued Date : Mar. 12, 2015

Report No.: FR511905B

Report Version : Rev. 01