



Report No. : FA410301


Appendix D. Test Setup Photos





Right Cheek

Right Tilted






Left Cheek

Left Tilted

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: ZC4S220 Page Number : D1 of D2
Report Issued Date : Jan. 24, 2014
Report Version : Rev. 01





Report No. : FA410301

Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap







Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: ZC4S220

Page Number : D2 of D2 Report Issued Date: Jan. 24, 2014 Report Version : Rev. 01