

US Jetting Surveillance Failure Follow Up Report FCC ID: ZC5022-GEN2-FP TC Code: TC580710

Prepared by:_ Jeff Woods CB Manager ACS, Inc.

De Will

This test report shall not be reproduced except in full. This report may be reproduced in part with prior written consent of ACS, Inc. The results contained in this report are representative of the sample(s) submitted for evaluation.

This report contains 3 pages

I have finally heard back from the grantee. Here are their responses to your questions.

How many devices have been sold?

From January of 20012 to present we have sold 16.

Has the grantee stopped marketing the Non-compliant device? Sales of the device are suspended pending testing.

What does the grantee propose on fixing the non-compliant devices sold? **Fix is pending test to determine issue.**

Is there a plan to recall, replace or fix them?

Again this is dependent on test to determine the issue and how best to proceed.

Grantee has contacted our lab about scheduling some test time to find a fix. I will follow up with FCC when I get the results of that testing.

END REPORT