

Page : 1 of 4

Issued date : Oct. 26, 2018 FCC ID : ZDL353B

Appendix I Radiated Spurious Emission Setup Configurations





Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



Page : 2 of 4

Issued date : Oct. 26, 2018 FCC ID : ZDL353B







Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000
Facsimile (FAX) :+886-3-583-7948



Page : 3 of 4

Issued date : Oct. 26, 2018 FCC ID : ZDL353B

Appendix II AC Power Line Conducted Emission Setup Configurations





Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



Page : 4 of 4

Issued date : Oct. 26, 2018 FCC ID : ZDL353B

