

## **INTERTEK TESTING SERVICES**

Report No.: HK11080818-1 Sample No.: 1/2 (Dongle)





Bandedge Plot - Pursuant to FCC Part 15 Section 15. 249 Requirement

Code: FCC15C\_f / Effective Date: 24 Jun 2011 ( of )