



775 Montague Expressway Milpitas, CA 95035 Tel: 408-526-1188 Fax: 408-526-1088 Email: TCB@siemic.com

Models difference delcaration

2013/5/31

To: Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road

Columbia, MD

FCC ID: ZDMBF40808183

Dear Sirs,

Our products with the above FCC ID models are defined: **BF4080**, **BF4083**, **BF4081**,

BF4080, **BF4083**, **BF4081** All hardware components are in design, circuitry and construction electrical identical.

BF4080, **BF4083**, **BF4081**, All RF modules are identical are in design, circuitry and construction electrical identical.

Only different in

BF4083 has an additional alternate external plastic cover.

BF4081 has an additional rechargeable battery module.

If you have any questions, please feel free to contact me at the address shown below.

Yours sincerely, Signatory

Signature

Signature



Name: Paul Franzosa

Title: Sr. Director of Product Development

Address: 745 Boylston Street, Boston, Massachusetts, United States 02116