# Precision Location Ultra Wideband System (PLUS™)

Precision Real-Time Location System

# System Manual



#### **PLUS Location Systems**

Cummings Research Park 4955 Corporate Drive Huntsville, AL 35805 USA

http://www.PLUS-ls.com

Tel: +1.256.922.9229 +1.888.826.8378

Fax: +1.256.922.0387

#### **Nondisclosure Provisions**

This manual is confidential and is governed by the terms of the Nondisclosure Agreement and the Partner Agreement currently in effect between the parties.

#### Copyright

©2001-2007 Time Domain Corporation. All rights reserved.

#### **Trademarks**

Time Domain® and PulsON® are registered trademarks of Time Domain Corporation. Ethernet® is a registered trademark of Xerox Corporation. "PulsON Triangle" logo and PLUS<sup>TM</sup> are trademarks of Time Domain Corporation. Any trademarks, trade names, service marks or service names owned or registered by any other company and used in this manual are the property of its respective company.

#### Rights

Rights to use this documentation are set forth in the Terms and Conditions accompanying the PLUSTM hardware.

#### **Product Safety Notice**

This device is listed under the ETL mark as Information Technology Equipment.

#### **Regulatory Notice**

<u>U.S. Operation</u>: This device complies with Part 15 of the FCC Rules. Operation is subject to the following conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. (3) Operation on board an aircraft or a satellite is prohibited. (4) Devices operating under this section may not be employed for the operation of toys.

Operation in disregard of these conditions is a violation of 47 U.S.C. 301 and could subject the operator to serious legal penalties. Disassembling or modifying the unit will void FCC compliance and void Time Domain warranty provisions.

**Non-U.S. Operation:** PulsON® technology has not been authorized for use or commercial exploitation under the regulations of any non-US government agency. Please confer with your government's regulatory agency to ensure proper authorizations are obtained.

#### **Table of Contents**

1.	OVERVIEW 9		
1.1	Manual Contents	Error! Bookmark not defined.	
1.2.1 1.2.2 1.2.3 1.2.4 1.2.5	P. Reader	Error! Bookmark not defined. Error! Bookmark not defined. Error! Bookmark not defined. Error! Bookmark not defined.	
1.3.1 1.3.2 1.3.3 1.3.4 1.3.5 1.3.6	Location Software PC	Error! Bookmark not defined Error! Bookmark not defined Error! Bookmark not defined Error! Bookmark not defined Error! Bookmark not defined.	
2. PLUS SYSTEM INSTALLATION 9			
2.1	Pre-Installation Site Survey	Error! Bookmark not defined.	
2.2	Reader Placement and Wiring Diagram	Error! Bookmark not defined.	
2.3.1 2.3.2 2.3.3 2.3.4 2.3.5 2.3.6	Installing and Powering the SDP Configuring Reader and Location Engine IP Addresses Ceiling Installation of Readers and Antennas Surveying Readers and Generating Coordinates	Error! Bookmark not defined. Error! Bookmark not defined. Error! Bookmark not defined. Error! Bookmark not defined. Error! Bookmark not defined.	
2.4.1 2.4.2 2.4.3 2.4.4 2.4.5	Check Reader Communications	Error! Bookmark not defined. Error! Bookmark not defined. Error! Bookmark not defined. Error! Bookmark not defined.	
2.5 2.5.1 2.5.2 2.5.3 2.6	2 Calibration Tag Configuration	Error! Bookmark not defined. Error! Bookmark not defined. Error! Bookmark not defined.	
2.6.1	9		

2.6.2 Viewing Calibration Tags	Error! Bookmark not defined.			
3. PLUS READER DATA INTERFACE 11				
3.1 Overview	Error! Bookmark not defined.			
3.2 Network Configuration Options	Error! Bookmark not defined.			
3.2.1 Reader IP Address	Error! Bookmark not defined.			
3.2.2 Location Engine IP Address				
3.2.3 Reader Port Assignments	Error! Bookmark not defined.			
2.2 DC 222 I				
3.3 RS-232 Interface				
3.3.1 RS-232 Port Connection Parameters				
3.3.2 Terminal Connection Login				
5.5.5 Terminal Connection Commands	Error: Bookmark not defined.			
3.4 Detailed Interface Description	Error! Bookmark not defined			
3.4.1 TOA Packet Format				
3.4.2 Commands and Responses				
3.4.3 Reader Alarms				
4. PLUS LOCATION SOFTWARE LIBRARY 12				
4.1 Introduction	Emant Dealtment not defined			
4.1 Introduction	Error! Bookmark not defined.			
4.2 PLUSTagTracker Object	Error! Bookmark not defined			
4.2.1 Function Interfaces	Error! Bookmark not defined.			
4.2.2 Property Interfaces				
4.2.3 Event Interfaces				
4.2.5 Event interfaces				
4.3 PLUSSysInterface Object	Error! Bookmark not defined.			
4.3.1 Function Interfaces	Error! Bookmark not defined.			
4.3.2 Property Interfaces	Error! Bookmark not defined.			
4.3.3 Event Interfaces	Error! Bookmark not defined.			
4.4 C# Sample Application Overview				
4.4.1 Operating the Sample Application				
4.4.2 Code Walkthrough	Error! Bookmark not defined.			

5.1	Overview	Error! Bookmark not defined.
5.2.1 5.2.2 5.2.3 5.2.4	FileViewSettings	Error! Bookmark not defined.
5.3	Toolbar	Error! Bookmark not defined.
5.4	Status Bar	Error! Bookmark not defined.
5.5	Graphical View Frame	Error! Bookmark not defined.
5.6	List View Frame	Error! Bookmark not defined.
5.7	Message View Frame	Error! Bookmark not defined.
5.8 5.8.1 5.8.2	Raw Data	Error! Bookmark not defined. Error! Bookmark not defined. Error! Bookmark not defined.
5.9	Troubleshooting the Visualizer	Error! Bookmark not defined.

### **Table of Figures**

Figure 1-1: PLUS SDP, Readers, and Tags	Error! Bookmark not defined.
Figure 1-2: PLUS Interface Layers	Error! Bookmark not defined.
Figure 2-1: Hardware Connections for a Four-Reader System	Error! Bookmark not defined.
Figure 2-2: Hardware Placement for a Four-Reader System	Error! Bookmark not defined.
Figure 2-3: Tracking Precision Relative to Reader Geometry	Error! Bookmark not defined.
Figure 2-4: Three Readers per SDP Port	Error! Bookmark not defined.
Figure 2-5: Four Readers Per SDP Port	Error! Bookmark not defined.
Figure 2-6: Five Readers Per SDP Port	Error! Bookmark not defined.
Figure 2-7: Six Readers Per SDP Port	Error! Bookmark not defined.
Figure 2-8: Reader and Location Engine IP Address Configuration.	Error! Bookmark not defined.
Figure 2-9: Reader Connection	Error! Bookmark not defined.
Figure 2-10: Antenna Frame and Drop Panel	Error! Bookmark not defined.
Figure 2-11: Frame Orientation	Error! Bookmark not defined.
Figure 2-12: Drop Panel Installation (shown with no Receiver moundefined.	tted) Error! Bookmark not
Figure 2-13: Closed Panel	Error! Bookmark not defined.
Figure 2-14: Unterminated Ethernet Cables	Error! Bookmark not defined.
Figure 2-15: TCP/IP Properties	Error! Bookmark not defined.
Figure 2-16: Visualizer Application	Error! Bookmark not defined.
Figure 2-17: Set Data Input	Error! Bookmark not defined.
Figure 2-18: Reader Communications in List View English/Metric S <b>defined.</b>	ettings Error! Bookmark not
Figure 2-19: Setting English/Metric Units	Error! Bookmark not defined.
Figure 2-20: Reader Configuration (unconfigured)	Error! Bookmark not defined.
Figure 2-21: Reader Configuration (complete)	Error! Bookmark not defined.
Figure 2-22: Floor Plan Data	Error! Bookmark not defined.
Figure 2-23: Inadequate Calibration Tag Coverage	Error! Bookmark not defined.
Figure 2-24: Adequate Calibration Tag Coverage	Error! Bookmark not defined.
Figure 2-25: Calibration Assist Mode	Error! Bookmark not defined.
Figure 2-26: Tag Configuration	Error! Bookmark not defined.
Figure 2-27: Calibration Window	Error! Bookmark not defined.
Figure 2-28: Reader Disabled Message	Error! Bookmark not defined.
Figure 2-29: Calibration Complete	Error! Bookmark not defined.

Figure 2-30: 2D MapView Settings	Error! Bookmark not defined.
Figure 2-31: Tracking and Displaying Calibration Tags	Error! Bookmark not defined.
Figure 2-32: Tag Statistics	Error! Bookmark not defined.
Figure 2-33: Intersection of TDOA Lines	Error! Bookmark not defined.
Figure 2-34: TDOA Statistics	Error! Bookmark not defined.
Figure 2-35: Position Statistics	Error! Bookmark not defined.
Figure 2-36: Filter Settings	Error! Bookmark not defined.
Figure 2-37: Data Logging	Error! Bookmark not defined.
Figure 2-38: Reader List View	Error! Bookmark not defined.
Figure 2-39: Opening a Command Window	Error! Bookmark not defined.
Figure 2-40: Pinging Reader with IP 10.1.4.11	Error! Bookmark not defined.
Figure 3-1: PLUS Interface Layers – Reader Data Interface	Error! Bookmark not defined.
Figure 3-2: changeIp and solverIp Commands	Error! Bookmark not defined.
Figure 3-3: TOA Packet Format	Error! Bookmark not defined.
Figure 3-4: Reader Commands	Error! Bookmark not defined.
Figure 3-5: Alarm Status and Alarm Enable Word Bit Position Defined.	nition Error! Bookmark not
Figure 4-1: PLUS Interface Layers – Location Software Library	Error! Bookmark not defined.
Figure 4-2: C# Sample Application Screenshot	Error! Bookmark not defined.
Figure 5-1: PLUS Interface Layers – Visualizer	Error! Bookmark not defined.
Figure 5-2: Visualizer Control Window	Error! Bookmark not defined.
Figure 5-3: Menu Bar	Error! Bookmark not defined.
Figure 5-4: File Menu.	Error! Bookmark not defined.
Figure 5-5: Logging Dialog	Error! Bookmark not defined.
Figure 5-6: View Menu	Error! Bookmark not defined.
Figure 5-7: Set Trail Length Dialog	Error! Bookmark not defined.
Figure 5-8: Presence Detect Example	Error! Bookmark not defined.
Figure 5-9: TDOA Statistics Dialog	Error! Bookmark not defined.
Figure 5-10: Tag Statistics Dialog	Error! Bookmark not defined.
Figure 5-11: Position Statistics Dialog	Error! Bookmark not defined.
Figure 5-12: Reader Stats Dialog	Error! Bookmark not defined.
Figure 5-13: Settings Menu	Error! Bookmark not defined.
Figure 5-14: Timeouts Dialog	Error! Bookmark not defined.
Figure 5-15: 2D MapView Settings	Error! Bookmark not defined.

Figure 5-16:	Set Data Input Dialog	Error! Bookmark not defined.
Figure 5-17: <b>defined</b>	PLUS Location Software Library Algorithm Filter Setti	ings Error! Bookmark not
Figure 5-18:	Configure Tags Dialog	Error! Bookmark not defined.
Figure 5-19:	Configure Readers Dialog	Error! Bookmark not defined.
Figure 5-20:	Help Menu	Error! Bookmark not defined.
Figure 5-21:	About Box Dialog	Error! Bookmark not defined.
Figure 5-22:	Toolbar Menu.	Error! Bookmark not defined.
Figure 5-23:	Translate Dialog	Error! Bookmark not defined.
Figure 5-24:	Tag List View	Error! Bookmark not defined.
Figure 5-25:	Reader List View	Error! Bookmark not defined.
Figure 5-26:	Reader Stats Showing Alarm Status	Error! Bookmark not defined.
Figure 5-27:	Status Bar	Error! Bookmark not defined.
Figure 5-28:	Graphical View Frame	Error! Bookmark not defined.
Figure 5-29:	List View Frame	Error! Bookmark not defined.
Figure 5-30:	Reader List View Menu	Error! Bookmark not defined.
Figure 5-31:	Tag List View Menu	Error! Bookmark not defined.
Figure 5-32:	Message View Frame	Error! Bookmark not defined.

## 1. Overview

Paste Section 1 of PLUS System Overview and Installation.doc

# 2. PLUS System Installation

Paste Section 2 of PLUS System Overview and Installation.doc

## 3. PLUS Reader Data Interface

Insert PLUS Reader Interface.doc

## 4. PLUS Location Software Library

Insert PLUS Location Software Library.doc

## 5. PLUS Visualizer

Insert PLUS Visualizer Users Manual.doc